

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI22003800/VQY3E2

**Date:** 06/06/2022

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR000104		
<b>Claimant Vehicle No :</b>	SHC3776P	<b>Insured Vehicle No :</b>	SLL1716G		
Date of Loss:	24/04/2022	Nature of Claim:	TP	Claim No:	M2201939

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3776P	Engine No:	G4LEKU422801
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU193241
Reg. Date:	31/08/2021 (Man. Year: 2019)	Odometer:	73473 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,260.12	3,784.28	475.84	11.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,770.00	1,410.00	360.00	20.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,041.12</b>	<b>5,205.28</b>	<b>835.84</b>	<b>13.84</b>
<b>+ GST 7.00/7.00% (S\$)</b>	422.88	364.37	58.51	13.84
<b>Nett Amount (S\$)</b>	<b>6,464.00</b>	<b>5,569.65</b>	<b>894.35</b>	<b>13.84</b>

### INSPECTION

Date of Assignment:	25/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2022)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC3776P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID COVER	Dented	2,549.70 FL	-	*2,480.40 FL
2	1		*REAR BUMPER ASSY	Cut	459.40 FL	-	*459.40 FL
3	10		*REAR BUMPER CLIPS	Necessary	220.00 FL	-	*22.00 FL
4	1		*REAR BUMPER TOW COVER	Cut	98.80 FL	-	*98.80 FL
5	1		*REAR BUMPER CENTRE GUIDE	Scratched	451.25 FL	-	*451.25 FL
6	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
7	1		*REVERSE SENSOR	Cut	180.00 F	-	*180.00 F
8	1		*REAR NUMBER PLATE	Cracked	50.00 F	-	*50.00 F
9	1		*FOG LAMP	Serviceable	201.50 FL	-	*- FL
10	1		*ANTENNA SMARTKEY	Serviceable	40.50 FL	-	*- FL
11	1		*BOOTLID EMBLEM - IONIQ	Necessary	31.30 FL	-	*31.30 FL
12	1		*BOOTLID EMBLEM - HYBRID	Necessary	24.30 FL	-	*24.30 FL
13	1		*BOOTLID EMBLEM - H	Not Necessary	28.00 FL	-	*- FL
14	1		*BOOTLID COMFORTDELGRO LOGO	Necessary	30.00 F	-	*30.00 F
15	1		*BOOTLID COMFORT TEL.NOS STICKER	Necessary	30.00 F	-	*30.00 F
16	1		*BOOTLID APPS LOGO	Necessary	40.00 F	-	*40.00 F
17	2		*WINDSCREEN GLASS SEALANT	Not Necessary	46.00 F	-	*- F
<b>Supplementary #1</b>							
18	1		*REAR BUMPER - STAY LH	Cracked	138.10 FL	-	*138.10 FL
19	1		*REAR BUMPER - BEAM	Dented	394.80 FL	-	*394.80 FL
20	1		*MOULDING REAR BUMPER LOWER CENTRE	Cut	155.00 FL	-	*155.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,218.65</b>	<b>4,635.35</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	958.53	851.07
<b>Total Parts (S\$)</b>	<b>4,260.12</b>	<b>3,784.28</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	900.00	700.00
2	SPRAYPAINT	New	600.00	500.00
3	TUFF KOTE	New	50.00	30.00
4	CHECK WIRING	New	50.00	30.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			1,770.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >