

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5414A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED	1,042.00	1,042.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	274.00	-
1	LEFT REAR TAIL LAMP	NOT NECESSARY	320.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	482.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	280.00	-
1	REAR BUMPER	BROKEN	600.00	570.00
1	REAR BUMPER LEFT RETAINER	BROKEN	30.00	30.00
1	REAR BUMPER LEFT REFLECTOR	BROKEN	40.00	40.00
1	SET REAR GLASS MOULDING (3 PCS)	NECESSARY	210.00	170.00
	LESS 25% DISCOUNT		-819.50	-463.00
			2,458.50	1,389.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	SET END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	15.00	-
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			280.00	265.00
	<u>LABOUR</u>			
	TO TUFF KOTE.		50.00	30.00
	TO TRANSFER TAILGATE TRIM BOARD, LOCK, HANDLE & MECHANISM PARTS.		60.00	30.00
	TO REFIT TAILGATE GLASS.		120.00	120.00
	TO REPAIR REAR END PANEL, REMOVE TAIL GATE, REAR BUMPER, REPLACE NECESSARY PARTS. ADJUST & ALIGN TAIL GATE AND REAR BUMPER.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		500.00	450.00
	TO PUTTY, RESPRAY PAINTING END PANEL, REAR BUMPER & TAIL GATE. TO POLISH.		600.00	600.00
			1,330.00	1,230.00
	GRAND TOTAL		4,068.50	2,884.00

Report Ref No. CS/SMR22003805/Ety3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMR22003805/Ety3n2



Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator