

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003806/UQY3N2**Date:** 19/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00014042100

Claimant Vehicle No : GBJ8511M **Insured Vehicle No :** PC3199K

Date of Loss: 07/04/2022 Nature of Claim: TP Claim No: SNM22D202715/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ8511M**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) Engine No: 4P10D80136

Reg. Date: 19/09/2019 (Man. Year: 2019) Chassis No: FEA01BA30268

Colour: White Odometer: 98346 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75R15 Rear Tyre Size: 195R15 (D)

Front Left Side: Bridgestone 8 mm Rear Left Side: Goform 8/8 mm

Front Right Side: Bridgestone 8 mm Rear Right Side: Goform 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,580.34	671.77	11,908.57	94.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	330.00	4,770.00	93.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,680.34	1,001.77	16,678.57	94.33
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	17,680.34	800.00	16,880.34	95.48

INSPECTION

Date of Assignment: 25/04/2022

Date Inspected: 26/04/2022 Inspected At: Kaizen Motors Pte Ltd (HQ)
68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT
Singapore 417896

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 May 2022)

Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ8511M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Not Necessary	1,148.50 F	*- FL
2	1		*FRONT WINDSCREEN RUBBER	Not Necessary	389.62 F	*- FL
3	1		*WIPER PANEL	Not Necessary	450.15 F	*- FL
4	2		*WIPER ARM	Not Necessary	750.62 F	*- FL
5	1		*WIPER MOTOR	Not Necessary	863.55 F	*- FL
6	1		*FRONT GRILLE	Not Necessary	325.55 F	*- FL
7	2		*FRONT HEADLAMP	Not Necessary	1,788.00 F	*- FL
8	2		*FRONT SIGNAL LAMP	Not Necessary	746.00 F	*- FL
9	2		*FRONT SIDE GARNISH PANEL	No such part	1,596.00 F	*- FL
10	1		*FRONT PANEL	Not Necessary	310.55 F	*- FL
11	1		*FRONT BUMPER	Not Necessary	1,286.00 F	*- FL
12	1		*FRONT CORNER PANEL GARNISH	N/s Cracked	1,506.00 F	*391.20 FL
13	2		*FRONT SIDE MIRROR N/S	Not Necessary	394.00 F	*- FL
14	1		*FRONT SIDE MIRROR ARM N/S	Bent	420.20 F	*401.50 FL
15	1		*FRONT SIDE MIRROR ROUND MIRROR N/S	Cracked	103.00 F	*103.00 FL
16	2		*FRONT SIDE MIRROR PANEL GARNISH	Not Necessary	352.60 F	*- FL
17	10		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
18	10		*FRONT SIDE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
19	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,580.34	895.70
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	223.93
Total Parts (S\$)	12,580.34	671.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	0.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT SECTION ASSY & PARTS	New	2,800.00	200.00
3	SPRAYPAINTING & PUTTY OF FRONT BUMPER & PANEL	New	1,500.00	130.00
4	REAR DIFFUSER, END PANEL, BUMPER GARNISH LABOUR FOR RETROFITTING MOULDING & SEAL	New	550.00	0.00
Gross Labour Cost (\$\$)			5,100.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >