

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003809/EQY3E2

Date: 19/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00078592200
Claimant Vehicle No: SBW71A Insured Vehicle No: SNB7966R
Date of Loss: 20/04/2022 Nature of Claim: TP Claim No: SNM22D202760/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBW71A**
Make & Model: INFINITI Q70, 2.5 (A) Engine No: VQ25847750A
Reg. Date: 27/03/2014 (Man. Year: 2013) Chassis No: JN1BCAY51Z0450026
Colour: Grey Odometer: 123332 km
Engine Capacity: 2496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50Z R18 Rear Tyre Size: 245/50Z R18
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,649.10	2,344.40	3,304.70	58.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,498.00	2,098.00	1,400.00	40.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,147.10	4,442.40	4,704.70	51.43
+ GST 7.00/7.00% (\$\$)	640.30	310.97	329.33	51.43
Nett Amount (\$\$)	9,787.40	4,753.37	5,034.03	51.43

INSPECTION

Date of Assignment: 25/04/2022
Date Inspected: 27/04/2022 Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)
45 Leng Kee Road
Singapore 159103
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,202.90 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2022)
Parts:	143	INFINITI Q70 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBW71A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER M37 M25	Dented	2,269.40 FS	*2,269.40 FS
2	15		*CLIP BUMPER REAR	Necessary	75.00 FS	*75.00 FS
3	1		*REAR BUMPER FOAM	* Check	417.50 FS	*- FS
4	1		*BRACKET BUMPER LH	* Check	70.20 FS	*- FS
5	1		*BRACKET BUMPER RH	* Check	70.20 FS	*- FS
6	1		*BUMPER BEAM REAR	* Check	1,489.00 FS	*- FS
7	1		*DIFFUSER ASSY	Not Necessary	101.80 FS	*- FS
8	4		*SENSOR-SCANNER	* Check	1,156.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,649.10	2,344.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REINFO SENSOR, ETC	New	1,200.00	800.00
2	TO SPRAY REAR BUMPER, REINFORCEMENT, ETC	New	1,800.00	800.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	498.00	498.00
Gross Labour Cost (\$)			3,498.00	2,098.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >