

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22003816/KTY3E2

Date: 06/06/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001866976		
Claimant Vehicle No :	SMR4302D	Insured Vehicle No :	FBQ4756M		
Date of Loss:	22/04/2022	Nature of Claim:	TP	Claim No:	273322

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4302D	Engine No:	G4FGHU621606
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU537239
Reg. Date:	07/09/2017 (Man. Year: 2017)	Odometer:	108711 km
Colour:	Metalic Light Gold		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,868.20	2,481.80	2,386.40	49.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,170.00	1,140.00	49.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,178.20	3,651.80	3,526.40	49.13

INSPECTION

Date of Assignment:	25/04/2022	TSR AUTOMOTIVE PTE LTD (HQ)
Date Inspected:	27/04/2022 Inspected At:	160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY
Estimated Period of Repair:	4.0 days	Singapore 575722

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$656.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR4302D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	980.00 FL	*- FL
2	1		*BOOTLID CENTER LOGO	Necessary	65.00 FL	*65.00 FL
3	1		*BOOTLID ELANTRA EMBLEM	Necessary	68.00 FL	*68.00 FL
4	1		*BOOTLID S EMBLEM	Necessary	55.00 FL	*55.00 FL
5	1		*BOOTLID LAMP RH	Cut	380.00 FL	*380.00 FL
6	1		*TAILLAMP RH	Cracked	588.90 FL	*588.90 FL
7	1		*TAILLAMP LOWER BRACKET RH	* Check	220.00 FL	*- FL
8	1		*REAR BUMPER	Cracked	785.60 FL	*785.60 FL
9	1		*REAR BUMPER REINFORCEMENT	* Check	480.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Scratched	285.00 FL	*285.00 FL
11	1		*REAR BUMPER LOWER GARNISH	Distorted / Cracked	468.50 FL	*468.50 FL
12	1		*REAR BUMPER BRACKET RH	* Check	120.00 FL	*- FL
13	1		*REAR BUMPER RETAINER RH	Serviceable	180.00 FL	*- FL
14	1		*END PANEL	Repair	680.00 FL	*- FL
15	1		*END PANEL TOP GARNISH	Serviceable	323.00 FL	*- FL
16	1		*SET REAR BUMPER SENSOR	Necessary	280.00 FS	*280.00 FS
17	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
					Sub Total (\$\$)	6,004.00 3,021.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,135.80 539.20
					Total Parts (\$\$)	4,868.20 2,481.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DO CUTTING WELDING, REPLACE REPAIR ACCIDENT AFFECTED AREA	New	1,000.00	500.00
2	TO REMOVE REFIX GARNISH, SIDE TRIM UPHOLSTERY ETC FOR ACCIDENT DAMAGE REPAIR	New	200.00	0.00
3	TO TRANSFER BOOTLID PARTS TO ANOTHER BOOTLID	New	100.00	0.00
4	CHECK LAMP WIRING SYSTEM FOR LAMPS, REPLACE SENSOR	New	150.00	70.00
5	TO DO ANTI RUST	New	60.00	0.00
6	TO DO SPRAY PAINTING FOR ACCIDENT AFFECTED AREA	New	800.00	600.00
Gross Labour Cost (\$\$)			2,310.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >