7/11/23, 10:57 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22003823/APA3Q2

11/07/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100427761 **Claimant Vehicle** SJE7073Z Insured Vehicle No: SKV3235Z

No:

Date of Loss: 02/02/2022 Nature of Claim: TP Claim No: 4888975819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE7073Z**

HONDA CIVIC, 1.8 L (A) Make & Model: R18A13032944 Engine No: Reg. Date: 03/05/2008 (Man. Year: 2008) Chassis No: JHMFD16308S215032

Colour: White Odometer: 295398 km

Engine Capacity: 1799 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,757.40	3,189.92	5,567.48	63.57
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,100.00	1,760.00	1,340.00	43.23
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,857.40	4,949.92	6,907.48	58.25
	Approved Total (Overridden) (S\$)		3,900.00		
	Nett Amount (S\$)	11,857.40	3,900.00	7,957.40	67.11
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 28/04/2022

Kt Motorwerk (HQ) 28/04/2022 Inspected At: Date Inspected:

Blk 3012 Bedok Industrial Park E, #01-2020

Singapore 489978

Estimated Period of Repair: 6.0 days

ADRIAN LING Manager: **CHEW HSIAO TONG** Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	638.40 F	*- FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
3	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	50.80 F	*- FL
4	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	1,200.00 FS	*- FS
5	1		*HEADLAMP	O/S Cut	1,979.20 F	*989.60 FL
6	2		*FRONT FENDER	Dented	901.60 F	*901.60 FL
7	2		*FRONT DOOR WING MIRROR	Damaged	1,096.20 F	*1,096.20 FL
8	1		*FRONT DOOR LH	Repair	981.20 F	*- FL
9	1		*ROCKER PANEL OUTER SKIRTING	Repair	650.00 FS	*- FS
10	1		*ROCKER PANEL OUTER SKIRTING CLIPS	Not Necessary	30.00 FS	*- FS
11	2		*FRONT WHEEL RIM	Cut	1,200.00 FS	*800.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/20.00% (S\$)			8,757.40 0.00	3,787.40 597.48	
	- List item Discount on Littems 0.00/20.00 // (54)					
				Total Parts (S\$)	8,757.40	3,189.92
			Report was unsubmitted during	g this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,400.00	900.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	50.00
5	TO TRANSFER DOOR FITTINGS	New	150.00	0.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
		Gross Labour Cost (S\$)	3,100.00	1,760.00
	Renort wa	s unsubmitted during this print-out.		

< END OF ESTIMATES >