

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003825/Uty3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 12/05/2022 SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. PC 8752E SHB 4772Z Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S2M03Z89 Excess (\$) 0.00 ONG KIAN THENG DERICK **Assign Date** 25/04/2022 Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI ROSA Make & Model 2998 C.C BE641JRMDEE Engine No. **HIDDEN** Year of Reg. 2019 Chassis No. BE641JK30642 Colour BROWN 103790 KM **IN ORDER** Odometer Steering **IN ORDER** NIL **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 205/85R16 YOKOHAMA 7 mm R/H Front Tyre 205/85R16 YOKOHAMA L/H Front Tyre 7 mm R/H Rear Tyre 205/85R16(D) YOKOHAMA 7/7 mm 205/85R16(D) YOKOHAMA 7/7 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. 5. **General Information Accident Date** 16/04/2022 **Inspect Date / Time** 04/05/2022 ( 12:50 PM ) 53 DEFU LANE 12, SINGAPORE 539144 Survey held at PIERRE@XCLUSIVE MOTORS PTE LTD Repairer

Remarks

**Estimate Days of Repair** 

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$300-\$500

Report Ref No. CS3/ASM22003825/Uty3e2

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Inspected By

5a.

5b.

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser