



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 5105P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	2,364.00	2,342.80
1	FL HEADLAMP NOZZLE COVER	SERVICEABLE	335.00	-
1	FL FOG LAMP COVER	DENTED / DISTORTED	577.00	464.40
	LESS 5% DISCOUNT		-	-140.36
			3,276.00	2,666.84
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
			35.00	35.00
LABOUR				
	TO REMOVE & TRANSFER FRONT WIRE HARNESS FOR HEADLAMP,HORN,FOG LAMP,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		480.00	280.00
	TO DISMANTLE AND RENEW FRONT BUMPER ASSY,RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	NOT NECESSARY	550.00	-
	TO SPRAY FRONT BUMPER,LOWER SPOILER AND WHEEL ARCH TRIMS.		600.00	450.00
			1,630.00	730.00
GRAND TOTAL			4,941.00	3,431.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS/SMO22003827/Kqy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.