

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003831/UTY3N2**Date:** 14/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00070332200
Claimant Vehicle No :	SGZ6152K	Insured Vehicle No :	SFS6060R
Date of Loss:	20/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202727/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ6152K	Engine No:	4G15HT0752
Make & Model:	MITSUBISHI COLT PLUS, 1.5 (A)	Chassis No:	Z27A0400519
Reg. Date:	09/11/2007 (Man. Year: 2007)	Odometer:	277847 km
Colour:	Red		
Engine Capacity:	1468 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,525.10	2,481.30	17,043.80	87.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	2,340.00	3,280.00	58.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,145.10	4,821.30	20,323.80	80.83
Approved Total (Overridden) (\$\$)		3,200.00		
Nett Amount (\$\$)	25,145.10	3,200.00	21,945.10	87.27

INSPECTION

Date of Assignment:	25/04/2022	
Date Inspected:	26/04/2022	Inspected At:
Estimated Period of Repair:	8.0 days	

13 KAKI BUKIT ROAD 4
BARTLEY BIZ CENTRE #01- 24
REPAIRER: ZOOM AUTOWERKS PTE LTD

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	144	mitsubishi colt plus 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ6152K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	118.00 FN	*- FN
2	1		*REAR TAILGATE	Not Necessary	885.00 FN	*- FN
3	1		*REAR TAILGATE LOCK	Not Necessary	339.00 FN	*- FN
4	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	329.00 FN	*- FN
5	1		*REAR TAILGATE RUBBER	Not Necessary	145.00 FN	*- FN
6	1		*REAR TAILLAMP-RH	Not Necessary	365.00 FN	*- FN
7	1		*REAR TAILLAMP PANEL	Repair	155.00 FN	*- FN
8	1		*REAR BUMPER	Distorted	625.00 FN	*585.00 FN
9	1		*REAR BUMPER LOWER DIFFUSER	Not fitted	385.00 FN	*- FN
10	1		*REAR BUMPER SIDE RETAINERS	O/s Cracked	85.00 FN	*35.00 FN
11	1		*REAR BUMPER SIDE GARNISH	Not Necessary	285.00 FN	*- FN
12	2		*REAR EXHAUST MOUNTINGS	Not Necessary	56.00 FN	*- FN
13	1		*REAR FENDER-RH	Repair	795.00 FN	*- FN
14	1		*REAR FENDER AIR GATE	Not Necessary	32.00 FN	*- FN
15	1		*REAR FENDER INNER SHIELD	Not Necessary	42.00 FN	*- FN
16	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	414.00 FN	*- FN
17	1		*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	310.00 FN	*- FN
18	1		*REAR FENDER WHEEL ARCH GARNISH	Warped	245.00 FN	*245.00 FN
19	1		*REAR WHEEL HUB C/W BEARING	Damaged	376.00 FN	*376.00 FN
20	1		*REAR SHOCK ABSORBER	Not Necessary	148.00 FN	*- FN
21	1		*REAR AXLE BEAM	Twisted	350.00 FN	*350.00 FN
22	1		*REAR CONTROL ARM	No such part	170.00 FN	*- FN
23	1		*REAR LOWER ARM	No such part	160.00 FN	*- FN
24	1		*FRONT BONNET	Repair	814.00 FN	*- FN
25	2		*FRONT BONNET HINGES	Not Necessary	86.00 FN	*- FN
26	1		*FRONT BONNET LOCK	Not Necessary	65.00 FN	*- FN
27	1		*FRONT BONNET RUBBER	Not Necessary	28.00 FN	*- FN
28	1		*FRONT HEADLAMPS	O/s Cracked	1,336.00 FN	*486.00 FN
29	2		*FRONT HEADLAMP PANELS	Repair	438.00 FN	*- FN
30	1		*FRONT GRILLE	Repair	262.00 FN	*- FN
31	1		*FRONT BUMPER	Torn	689.00 FN	*580.00 FN
32	1		*FRONT BUMPER BEAM	Repair	214.00 FN	*- FN
33	1		*FRONT BUMPER LOGO	Not Necessary	42.00 FN	*- FN
34	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	105.00 FN	*- FN
35	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	332.00 FN	*- FN
36	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	76.00 FN	*- FN
37	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	28.00 FN	*- FN
38	2		*FRONT FENDERS	Not Necessary	870.00 FN	*- FN
39	1		*FRONT FENDER WHEEL ARCH GARNISH	Not Necessary	285.00 FN	*- FN
40	1		*FRONT SUPPORT PANEL	Repair	484.00 FN	*- FN
41	1		*FRONT BRACE PANEL	Not Necessary	48.00 FN	*- FN
42	1		*AIR CON CONDENSER	Not Necessary	874.00 FN	*- FN
43	1		*AIR CON FAN ASSY	Not Necessary	421.00 FN	*- FN
44	1		*RADIATOR	Not Necessary	831.00 FN	*- FN
45	1		*RADIATOR FAN ASSY	Not Necessary	435.00 FN	*- FN
46	1		*INTER COOLER	Not Necessary	1,245.00 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*AIR CLEANER BOX	Not Necessary	219.00 FN	*- FN
48	1		*AIR INTAKE DUCT	Not Necessary	102.00 FN	*- FN
49	1		*FRONT WIPER TANK	Not Necessary	96.00 FN	*- FN
50	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
52	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
53	1		*SET REAR REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
54	1		*REAR EXHAUST SILENCER-SPORT	Not Necessary	1,450.00 FS	*- FS
55	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
56	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
57	1		*REAR WHEEL RIM	Repair	800.00 FS	*- FS
58	1		*FRONT BUMPER LOWER SPOILER SET	Repair	650.00 FS	*- FS
59	1		*FRONT NUMBER PLATE WITH HOLDER	Missing	50.00 FS	*40.00 FS
60	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	21,249.00	2,747.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,723.90	265.70
Total Parts (\$\$)	19,525.10	2,481.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
8	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	120.00	0.00
9	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
10	TO APPLY UNDERCOATING	New	250.00	0.00
11	PANEL BEATING	New	2,200.00	1,000.00
12	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,000.00	1,200.00
Gross Labour Cost (\$)			5,620.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >