12/8/22, 2:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22003833/APA3Q2

08/12/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900104722 **Claimant Vehicle** SLQ5716D Insured Vehicle No: SMM1712A No:

Date of Loss: 23/04/2022 Nature of Claim: ΤP Claim No: 7794769358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ5716D**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN038995

Reg. Date: 14/07/2017 (Man. Year: 2017) Chassis No: WAUZZZF44HA164740

Odometer: Colour: Blue 114250 km

Engine Capacity: 1395 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

205/60 R16 Front Tyre Size: 205/60 R16 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		16,712.00	2,087.20	14,624.80	87.51
Miscellaneous Items		0.00	0.00	0.00	
Labour		16,282.00	3,582.00	12,700.00	78.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	32,994.00	5,669.20	27,324.80	82.82
	+ GST 7.00/7.00% (S\$)	2,309.58	396.84	1,912.74	82.82
	Nett Amount (S\$)	35,303.58	6,066.04	29,237.54	82.82
	+ Car Rental (5.0 x S	\$100.00/day) (S\$)	500.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	6,568.04		

INSPECTION

Date of Assignment: 28/04/2022

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Date Inspected: 28/04/2022 Inspected At:

Singapore 408699

Estimated Period of Repair: 5.0 days

ADRIAN LING CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,609.00 FS	*2,087.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*-FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER GUIDE SECTION UPPER -LH	Not Necessary	49.00 FS	*- FS
5	1		*REAR BUMPER GUIDE SECTION -LH	Not Necessary	26.00 FS	*- FS
6	1		*REAR FENDER -LH	Repair	4,357.00 FS	*- FS
7	1		*GROMMET	Not Necessary	2.00 FS	*- FS
8	1		*REAR WINDSCREEN	Not Necessary	1,287.00 FS	*-FS
9	1		*QUARTER WINDOW -RH	Not Necessary	685.00 FS	*- FS
10	2		*PRIMER	Not Necessary	44.00 FS	*- FS
11	1		*REAR DOOR -LH	Repair	3,431.00 FS	*- FS
12	1		*REAR DOOR OUTER SEAL -LH	Not Necessary	229.00 FS	*- FS
13	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
15	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
16	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
17	1		*REAR DOOR CATCH LH	Not Necessary	134.00 FS	*- FS
18	1		*REAR DOOR HANDLE TRIM PLATE -LH	Not Necessary	98.00 FS	*- FS
19	1		*REAR DOOR HANDLE COVER -LH	Repair	7.00 FS	*- FS
20	1		*REAR DOOR HANDLE HOUSING -LH	Not Necessary	9.00 FS	*- FS
21	1		*REAR WHEEL HOUSING LINER -LH	Not Necessary	260.00 FS	*- FS
22	1		*ALUMINIUM RIM	Not Necessary	1,020.00 FS	*- FS
23	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
24	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
25	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
26	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
27	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*-FS
28	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*-FS
29	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*-FS
30	1		*SUNDRIES	Not Necessary	500.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett.			
				Total Parts (S\$)	16,712.00	2,087.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	0.00
TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	0.00
TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	0.00
TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY	New	1,400.00	0.00
TO REMOVE AND REINSTALL REAR SEAT ,BACK REST HAT TRAY ,ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
TO REMOVE AND TRANSFER LHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGE	New	350.00	0.00
TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR TO CUT OUT AND WELD LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
TO RESPRAY REAR BUMPER ,LHS REAR FENDER LHS REAR DOOR DOOR HANDLE LHS SILL PANEL DOOR ENTRANCE DRAIN CHANNEL ROOF CHANNEL AND REAR END PANELLING	New	5,500.00	1,750.00
TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour	Cost (S\$)	16,282.00	3,582.00
Report was unsubmitted during this r	orint-out		
	DUI Items TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY TO REMOVE AND REINSTALL REAR SEAT BACK REST HAT TRAY BACD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGE TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR TO CUT OUT AND WELD LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED TO RESPRAY REAR BUMPER ,LHS REAR FENDER LHS REAR DOOR DOOR HANDLE LHS SILL PANEL DOOR ENTRANCE DRAIN CHANNEL ROOF CHANNEL AND REAR END PANELLING TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT TO CARRY OUT DIAGNOSTIC CHECK Gross Labour	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS New TO DISLODGE AND REINSTALL REAR WINDSCREEN AND 1/4 GLASS New TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY TO REMOVE AND REINSTALL REAR SEAT BACK REST HAT TRAY ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGE TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR TO CUT OUT AND WELD LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED TO RESPRAY REAR BUMPER ,LHS REAR FENDER LHS REAR DOOR DOOR HANDLE LHS SILL PANEL DOOR ENTRANCE DRAIN CHANNEL ROOF CHANNEL AND REAR END PANELLING TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT New	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID New 360.00 KICK SENSOR TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE New 600.00 RENEWAL OF LHS REAR FENDER TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 COUNTY WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS New 400.00 TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS NEW 1,400.00 BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY TO REMOVE AND REINSTALL REAR SEAT ,BACK REST HAT TRAY ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO REMOVE AND TRANSFER LHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGE TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR TO CUT OUT AND WELD LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED TO RESPRAY REAR BUMPER, LHS REAR FENDER LHS REAR DOOR DOOR HANDLE LHS SILL PANEL DOOR ENTRANCE DRAIN CHANNEL ROOF CHANNEL AND REAR END PANELLING TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT New 192.00 Gross Labour Cost (S\$) 16,282.00

< END OF ESTIMATES >