

## Vehicle Damage Assessment Report for [SLK9560R]

Estimate Created: 26/04/2022 02:18 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 17/04/2023 14:53 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | III                          | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |         |
|----------------------|----------|--------------------|---------|
| Brand                | Toyota   | Model              | Corolla |
| Engine Type          |          |                    |         |
| License Plate Number | SLK9560R | VIN (or Chassis #) |         |

### Vehicle Condition

|                 |                 |               |
|-----------------|-----------------|---------------|
| Damaged Diagram | Odometer        | 122,735.00 Km |
|                 | Tyres Condition |               |
|                 | Front Left      | mm            |
|                 | Front Right     | mm            |
|                 | Rear Left       | mm            |
|                 | Rear Right      | mm            |

### Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$5,000.00 WITH 6 WORKING DAYS

Insurlogic 4 (17/04/2023 14:53)

**Parts**

| Description                       | Number/Type | Qty | Cost   | Markup/Disc. % | Sum    |
|-----------------------------------|-------------|-----|--------|----------------|--------|
| Rear bumper                       |             | 1   | 556.40 | -25.00 %       | 417.30 |
| Rear bumper side holder           |             | 2   | 60.40  | -25.00 %       | 90.60  |
| LH Rear bumper reflector          |             | 1   | 59.80  | -25.00 %       | 44.85  |
| Rear bumper reinforcement         |             | 1   | 399.50 | -25.00 %       | 299.63 |
| Rear bumper reinforcement bracket |             | 1   | 68.20  | -25.00 %       | 51.15  |
| Reverse sensor                    |             | 1   | 265.30 | -25.00 %       | 198.98 |
| Rear end panel                    |             | 1   | 670.00 | -25.00 %       | 502.50 |
| Rear end panel top garnish        |             | 1   | 185.90 | -25.00 %       | 139.43 |
| LH Taillamp                       |             | 1   | 394.50 | -25.00 %       | 295.88 |
| Bootlid                           |             | 1   | 781.10 | -25.00 %       | 585.83 |
| Bootlid lock                      |             | 1   | 399.50 | -25.00 %       | 299.63 |
| Toyota Logo                       |             | 1   | 58.90  | -25.00 %       | 44.18  |
| Corolla wording                   |             | 1   | 39.30  | -25.00 %       | 29.48  |
| Altis wording                     |             | 1   | 43.60  | -25.00 %       | 32.70  |

Parts Subtotal 3,032.14

**Materials**

| Description                      | Number/Type | Qty | Cost   | Markup/Disc. % | Sum    |
|----------------------------------|-------------|-----|--------|----------------|--------|
| Rear bumper clips                |             | 1.0 | 30.00  | 0.00 %         | 30.00  |
| Rear bumper lower spoiler        |             | 1.0 | 950.00 | 0.00 %         | 950.00 |
| Rear end panel top garnish clips |             | 1.0 | 20.00  | 0.00 %         | 20.00  |
| Rear end panel sealant           |             | 1.0 | 60.00  | 0.00 %         | 60.00  |

Materials Subtotal 1,060.00

**Labor****Replace/RnR**

| Description                            | Type | Cost   | Markup/Disc % | Price  |
|----------------------------------------|------|--------|---------------|--------|
| Panel beating                          | RnR  | 900.00 | 0.00 %        | 900.00 |
| Check wiring                           | RnR  | 30.00  | 0.00 %        | 30.00  |
| To remove and reinstall reverse sensor | RnR  | 50.00  | 0.00 %        | 50.00  |
| To tuff coat                           | RnR  | 60.00  | 0.00 %        | 60.00  |
| To remove upholstery                   | RnR  | 60.00  | 0.00 %        | 60.00  |
| To transfer bootlid fittings           | RnR  | 60.00  | 0.00 %        | 60.00  |

**Paint**

| Description    | Paint Type    | Cost    | Markup/Disc %          | Price    |
|----------------|---------------|---------|------------------------|----------|
| Spray painting | Full spray    | 1000.00 | 0.00 %                 | 1,000.00 |
| Labor Rate     | S\$ 50 / Hour |         | General Labor Subtotal | 1,160.00 |
|                |               |         | Paint Labor Subtotal   | 1,000.00 |
|                |               |         | Labor Subtotal         | 2,160.00 |

**Summary**

|                |            |
|----------------|------------|
| Repair Cost    | 6,252.14   |
| Discount(20 %) | (1,250.42) |
|                | 5,001.72   |
| Excess         | (0.00)     |
| GST(0.00 %)    | 0.00       |
| Grand Subtotal | 5,001.72   |