

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003844/ANY3Q2**Date:** 30/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00133462101

**Claimant Vehicle No :** GBF8115U **Insured Vehicle No :** XE1247M

Date of Loss: 18/04/2022 Nature of Claim: TP Claim No: SNM22D202652/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBF8115U**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (M) Engine No: 1KD2678538

Reg. Date: 22/03/2017 (Man. Year: 2016) Chassis No: JTFAT35Y40K207417

Colour: Silver Odometer: 190294 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12

Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm

Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,390.15	4,896.65	4,493.50	47.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,620.00	740.00	31.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,750.15</b>	<b>6,516.65</b>	<b>5,233.50</b>	<b>44.54</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,200.00</b>		
<b>(\$\$)</b>	11,750.15	5,200.00	6,550.15	55.75
<b>+ GST 7.00/7.00% (\$\$)</b>	822.51	364.00	458.51	55.75
<b>Nett Amount (\$\$)</b>	<b>12,572.66</b>	<b>5,564.00</b>	<b>7,008.66</b>	<b>55.75</b>

**INSPECTION**

Date of Assignment: 25/04/2022

Date Inspected: 12/07/2022 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT  
AUTOHUB  
Singapore 417921

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 28 Sep 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF8115U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,116.70 FL	*1,116.70 FL
2	2		*REAR TAILGATE FLIP LOCK HANDLE L/R	Damaged	231.80 FL	*231.80 FL
3	4		*REAR TAILGATE HINGES	Not Necessary	230.80 FL	*- FL
4	1		*REAR TAILGATE LOWER PANEL	Dented	585.80 FL	*585.80 FL
5	1		*REAR TAILGATE TOYOTA STICKER	Necessary	238.90 FL	*238.90 FL
6	2		*REAR TAILLAMP L/R	Not Necessary	502.60 FL	*- FL
7	2		*SIDE GATE HINGES L/R	Not Necessary	795.60 FL	*- FL
8	1		*SIDE GATE L/R	N/S Dented	2,818.00 FL	*1,409.00 FL
9	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
10	1		*REAR TAILGATE 13 PAX STICKER	Necessary	25.00 FS	*15.00 FS
11	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
12	1		*REAR TAILGATE ALUMINIUM PANEL	Bent	800.00 FS	*300.00 FS
13	1		*SET REAR TAILGATE ALUMINIUM PANEL REPAIR KIT	Necessary	120.00 FS	*40.00 FS
14	1		*REAR TAILGATE LOWER PANEL WARNING SIGN STICKER	Necessary	380.00 FS	*80.00 FS
15	2		*SET SIDE GATE ALUMINIUM PANEL REPAIR KIT L/R	Necessary	300.00 FS	*60.00 FS
16	2		*SIDE GATE ART WORK STICKER L/R	Necessary	1,000.00 FS	*600.00 FS
17	2		*SIDE GATE TOP ALUMINIUM RAIL L/R	Bent	1,600.00 FS	*900.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,020.20</b>	<b>5,792.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,630.05	895.55
<b>Total Parts (S\$)</b>	<b>9,390.15</b>	<b>4,896.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,360.00</b>	<b>1,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >