

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003847/AEA3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210033699
Claimant Vehicle No :	SMS1602C	Insured Vehicle No :	GBL2147K
Date of Loss:	21/04/2022	Nature of Claim:	TP
		Claim No:	9991706640SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS1602C	Engine No:	G4FGKU473049
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU009209
Reg. Date:	13/02/2020 (Man. Year: 2019)	Odometer:	43851 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	RAPID 6 mm	Rear Left Side:	RAPID 6 mm
Front Right Side:	RAPID 6 mm	Rear Right Side:	RAPID 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,118.08	5,998.24	6,119.84	50.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,970.00	1,910.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,998.08	7,968.24	8,029.84	50.19
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	15,998.08	6,300.00	9,698.08	60.62
+ GST 7.00/7.00% (S\$)	1,119.87	441.00	678.87	60.62
Nett Amount (S\$)	17,117.95	6,741.00	10,376.95	60.62
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,283.00		
Global Sum Settlement (S\$)		7,280.00		

INSPECTION

Date of Assignment:	25/04/2022	
Date Inspected:	25/04/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	2,049.80 FL	*1,782.00 FL
2	1		*REAR BOOTLID LOCK	Damaged	116.20 FL	*116.20 FL
3	2		*REAR BOOTLID HINGE	Not Necessary	188.60 FL	*- FL
4	2		*REAR BOOTLID LAMP	Not Necessary	569.80 FL	*- FL
5	1		*REAR BOOTLID E EMBLEM LOGO	Necessary	196.20 FL	*55.00 FL
6	1		*REAR BOOTLID E EMBLEM AVANTE	Necessary	51.20 FL	*51.20 FL
7	1		*REAR BOOTLID INNER TRIM	Torn	166.80 FL	*166.80 FL
8	1		*REAR WEATHER STRIPE	Cut	125.20 FL	*125.20 FL
9	1		*REAR BUMPER	Distorted	498.80 FL	*498.80 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
11	1		*REAR BUMPER LOWER GARNISH	Distorted	340.60 FL	*340.60 FL
12	2		*REAR BUMPER REFLECTOR	Cracked	403.00 FL	*403.00 FL
13	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	72.20 FL	*36.10 FL
14	4		*REAR BUMPER BRACKET	Damaged	314.40 FL	*90.00 FL
15	1		*REAR BUMPER NUMBER PLATE GARNISH	Deformed	45.90 FL	*45.90 FL
16	2		*REAR NUMBER PLATE LAMP	Cracked	64.60 FL	*64.60 FL
17	2		*REAR TAILLAMP	Cut	2,104.20 FL	*2,104.20 FL
18	2		*REAR TAILLAMP INNER PANEL	Repair	386.20 FL	*- FL
19	1		*REAR END PANEL	Distorted	454.60 FL	*454.60 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	114.50 FL	*114.50 FL
21	1		*REAR SPARE TYRE COMPARTMENT PANEL	Repair	640.80 FL	*- FL
22	1		*REAR SPARE TYRE TOP BOARD	Deformed	266.80 FL	*266.80 FL
23	2		*REAR FENDER	Repair	3,572.60 FL	*- FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	415.80 FL	*- FL
25	1		*REAR KEYLESS SENSOR	Not Necessary	81.50 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
28	1		*REAR BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	1		*REAR BOOTLID REVERSE SENSOR	Not Necessary	420.00 FS	*- FS
31	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
32	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS
34	1		*REAR NUMBER PLATE WITH CASING	Bent	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,825.10	7,400.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,707.02	1,402.06
Total Parts (\$\$)	12,118.08	5,998.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,000.00	1,000.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	80.00
5	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
6	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING	New	150.00	60.00
Gross Labour Cost (\$\$)			3,880.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >