

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22003848/UCY3N2**Date:** 01/07/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001077946
Claimant Vehicle No :	SLM6914M	Insured Vehicle No :	SLF275A
Date of Loss:	07/04/2022	Nature of Claim:	TP
		Claim No:	272963

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6914M	Engine No:	2ZR1942377
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W70J006737
Reg. Date:	06/04/2017 (Man. Year: 2017)	Odometer:	93073 km
Colour:	Beige		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Linglong 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,844.00	556.25	9,287.75	94.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	710.00	3,930.00	84.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,484.00	1,266.25	13,217.75	91.26
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	14,484.00	1,000.00	13,484.00	93.10
+ GST 7.00/7.00% (\$\$)	1,013.88	70.00	943.88	93.10
Nett Amount (\$\$)	15,497.88	1,070.00	14,427.88	93.10

INSPECTION

Date of Assignment:	26/04/2022	Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	27/04/2022 Inspected At:	23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Estimated Period of Repair:	2.0 days	Singapore 415933

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6914M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,340.00 FL	*- FL
2	1		*TAILGATE LOGO	Not Necessary	73.00 FL	*- FL
3	2		*TAILGATE LAMP	Not Necessary	596.00 FL	*- FL
4	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	124.00 FL	*- FL
5	1		*TAILGATE OUTER MOULDING	Not Necessary	290.00 FL	*- FL
6	1		*TAILGATE OUTER LOCK BUTTOM	Not Necessary	210.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Not Necessary	398.00 FL	*- FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
9	1		*TAILGATE WEATHER STRIP	Not Necessary	320.00 FL	*- FL
10	1		*TAILGATE INNER BOARD	Not Necessary	450.00 FL	*- FL
11	2		*TAILGATE DAMPER	Not Necessary	392.00 FL	*- FL
12	1		*TAILGATE DETECTOR	Not Necessary	395.00 FL	*- FL
13	1		*TAILGATE WIPER MOTOR	Not Necessary	720.00 FL	*- FL
14	1		*TAILGATE WIPER MOTOR HEAD COVER	Not Necessary	42.00 FL	*- FL
15	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	140.00 FL	*- FL
16	1		*REAR BUMPER	Dented/Deformed	580.00 FL	*580.00 FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
18	1		*REAR BUMPER SIDE RETAINER	N/s Bent	190.00 FL	*95.00 FL
19	2		*REAR BUMPER BRACKET	Not Necessary	210.00 FL	*- FL
20	2		*REAR FENDER INNER COWLING	Not Necessary	760.00 FL	*- FL
21	2		*REAR FENDER INNER TRIM	Not Necessary	1,660.00 FL	*- FL
22	1		*REAR END PANEL	Repair	495.00 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Not Necessary	295.00 FL	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	598.00 FL	*- FL
25	1		*REAR FLOOR PANEL SIDE BOARD RH	Not Necessary	125.00 FL	*- FL
26	1		*REAR FLOOR PANEL TOP INNER SUPPORT	Not Necessary	498.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
29	1		*SET TAILGATE INNER BOARD CLIP	Not Necessary	60.00 FS	*- FS
30	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
32	1		*TAILGATE EMBLEM VALVE MATIC (SPECIAL TYPE)	Not Necessary	120.00 FS	*- FS
33	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
34	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
35	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
36	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR MOULDING (SPECIAL TYPE)	Not Necessary	120.00 FS	*- FS
38	1		*SET REVERSE SENSOR	Serviceable	220.00 FS	*- FS
39	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,612.00	725.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,768.00	168.75
Total Parts (\$)	9,844.00	556.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	1,600.00	280.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	300.00
3	TUFF COAT	New	250.00	0.00
4	WIRING AND BULB CHECK	New	180.00	0.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING T	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	REMOVE AND REFIX REVERSE CAMERA	New	120.00	0.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	80.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,640.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >