

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003849/APA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070058399
Claimant Vehicle No :	SMW1209J	Insured Vehicle No :	SMT1625G
Date of Loss:	13/04/2022	Nature of Claim:	TP
		Claim No:	5721223573SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1209J	Engine No:	L13B1516272
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GR11012328
Reg. Date:	02/11/2020 (Man. Year: 2020)	Odometer:	26309 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,797.90	5,783.68	4,014.22	40.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,200.00	1,330.00	37.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,327.90	7,983.68	5,344.22	40.10
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	13,327.90	6,300.00	7,027.90	52.73
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,707.45		

INSPECTION

Date of Assignment:	25/04/2022	Advance Auto Garage (HQ)
Date Inspected:	25/04/2022 Inspected At:	23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE
Estimated Period of Repair:	6.0 days	Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*REAR BUMPER	Distorted	859.10 F	*549.20 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	58.20 F	*58.20 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	131.80 F	*- FL
7	1		*REAR BUMPER IMPACT BRACKET	N/S Dented	170.00 F	*85.00 FL
8	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR END PANEL	Dented	540.50 F	*540.50 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	241.40 F	*241.40 FL
11	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
13	1		*REAR END PANEL BUZZER	Cracked	139.40 F	*139.40 FL
14	1		*REAR END PANEL ANTENNA SENSOR	Cracked	189.40 F	*189.40 FL
15	2		*TAILLAMP	N/S Cut / O/S Cracked	1,101.00 F	*1,101.00 FL
16	1		*TAILGATE	Dented	1,035.60 F	*1,035.60 FL
17	1		*TAILGATE LOCK	Damaged	245.40 F	*245.40 FL
18	1		*TAILGATE WEATHERSTRIPE	Cut	198.40 F	*198.40 FL
19	1		*TAILGATE INNER TRIM BOARD	Deformed	385.40 F	*385.40 FL
20	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*TAILGATE REFLECTOR	N/S Cut	900.20 F	*450.10 FL
22	1		*TAILGATE GLASS MOULDING	Necessary	188.40 F	*188.40 FL
23	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
24	1		*FIT EMBLEM	Necessary	48.90 F	*48.90 FL
25	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
26	1		*REAR FENDER INNER TRIM BOARD	N/S Cracked	791.20 F	*395.60 FL
27	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
28	1		*REAR FENDER INNER SHIELD LH	Torn	102.40 F	*102.40 FL
29	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
30	1		*SPARE TYRE PANEL TOP COVER	Deformed	295.90 F	*295.90 FL
31	1		*TOOLS TRAY SPONGE	Torn	304.40 F	*304.40 FL
32	1		*REAR EXHAUST PIPE	Not Necessary	694.80 F	*- FL
33	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	39.40 F	*- FL
34	1		*REAR EXHAUST PIPE GASKET	Not Necessary	36.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,797.90	7,094.60
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,310.92
Total Parts (S\$)	9,797.90	5,783.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE UPHOLSTERY	New	150.00	60.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,530.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >