

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22003851/UQY3N2**Date:** 19/05/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP318077
Claimant Vehicle No :	SJR6727J	Insured Vehicle No :	SMS1620A
Date of Loss:	25/04/2022	Nature of Claim:	TP
		Claim No:	MPC03360/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6727J	Engine No:	1NZX928311
Make & Model:	TOYOTA VIOS J AUTO, 1.5 (A)	Chassis No:	MR053HY9305118941
Reg. Date:	06/07/2009 (Man. Year: 2009)	Odometer:	235715 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	General 6 mm	Rear Left Side:	General 6 mm
Front Right Side:	General 6 mm	Rear Right Side:	General 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,765.80	2,821.37	6,944.43	71.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,990.00	1,380.00	40.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,135.80	4,811.37	8,324.43	63.37
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	13,135.80	3,800.00	9,335.80	71.07
+ GST 7.00/7.00% (S\$)	919.51	266.00	653.51	71.07
Nett Amount (S\$)	14,055.31	4,066.00	9,989.31	71.07

INSPECTION

Date of Assignment:	26/04/2022	
Date Inspected:	26/04/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2022)
Parts:	143	TOYOTA VIOS J AUTO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR6727J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.10 F	*- FL
2	1		*BOOTLID	Bent / Buckled	755.10 F	*621.10 FL
3	2		*BOOTLID HINGES	Repair	230.00 F	*- FL
4	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
5	1		*BOOTLID VIOS EMBLEM	Necessary	52.00 F	*52.00 FL
6	1		*BOOTLID TRD LOGO	Not fitted	60.00 F	*- FL
7	1		*BOOTLID OUTER HANDLE	Not Necessary	199.00 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	166.10 F	*166.10 FL
9	1		*BOOTLID INNER LOCK	Twisted / Bent	145.50 F	*145.50 FL
10	1		*REAR BUMPER	Deformed / Torn	488.10 F	*488.10 FL
11	1		*REAR BUMPER REFLECTORS	O/s Cracked/N/s Not Necessary	302.00 F	*151.00 FL
12	1		*REAR BUMPER SIDE RETAINERS	O/s Cracked/N/s Not Necessary	210.00 F	*85.00 FL
13	1		*REAR BUMPER CLIPS SET	Necessary	50.00 F	*50.00 FL
14	1		*REAR END PANEL	Dented / Bent	719.90 F	*580.20 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	166.80 F	*166.80 FL
16	1		*TAILLAMPS	O/s Cracked/N/s Not Necessary	710.20 F	*355.10 FL
17	2		*TAILLAMP HOUSING PANELS	Repair	420.00 F	*- FL
18	1		*REAR FLOOR PANEL	Repair	855.10 F	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Torn	315.00 F	*245.10 FL
20	1		*REAR FLOOR PANEL TOOLS SPONGES	O/s Torn/N/s Not Necessary	798.20 F	*254.00 FL
21	1		*REAR FLOOR PANEL TOOLS SPONGE INNER	Not Necessary	350.10 F	*- FL
22	1		*REAR SPARE TYRE SCREW CARRIER	Not Necessary	66.80 F	*- FL
23	1		*REAR EXHAUST	Not Necessary	655.10 F	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	50.00 F	*- FL
25	1		*REAR FENDER INNER TRIM	Not Necessary	332.10 F	*- FL
26	1		*REAR FENDER	Repair	899.10 F	*- FL
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 9,765.80 3,678.50
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 857.13

Total Parts (\$\$) 9,765.80 2,821.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX FUEL TANK	New	120.00	0.00
7	TO SPRAY RUST PROOFING	New	120.00	80.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,370.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >