

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003859/KVY3Q2**Date:** 03/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00006622101

Claimant Vehicle No : SLA9998P **Insured Vehicle No :** PC3142Z

Date of Loss: 23/03/2022 Nature of Claim: TP Claim No: SNM22D202036/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA9998P**

Make & Model: MERCEDES-BENZ E250, 2.0 SEDAN EDITION E (R18 LED SR) (A) Engine No: 27492030467839

Reg. Date: 03/02/2016 (Man. Year: 2015) Chassis No: WDD2120362B241397

Colour: Metallic Grey Odometer: 124516 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R18 Rear Tyre Size: 245/45Z R18

Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm

Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,077.10	5,615.70	5,461.40	49.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,470.00	1,020.00	40.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,567.10	7,085.70	6,481.40	47.77
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	13,567.10	5,650.00	7,917.10	58.36
+ GST 7.00/7.00% (S\$)	949.70	395.50	554.20	58.36
Nett Amount (S\$)	14,516.80	6,045.50	8,471.30	58.36

INSPECTION

Date of Assignment: 26/04/2022

Date Inspected: 26/04/2022 Inspected At: 160 SIN MING DRIVE, #02-20
SIN MING AUTOCITY
SINGAPORE 575722
Repairer :K.kim Hin Auto Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Nov 2022)

Parts: 143 MERCEDES-BENZ E250 2.0 SEDAN EDITION E (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA9998P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	2,015.00 FL	*1,900.00 FL
2	1		*REAR BUMPER LOWER TRIM	Serviceable	340.00 FL	*- FL
3	1		*REAR BUMPER PARKING SENSOR OUTER -LH	Missing	210.00 FL	*210.00 FL
4	6		*REAR BUMPER PARKING SENSOR SEALS	Necessary	54.00 FL	*54.00 FL
5	1		*REAR BUMPER SIDE BRACKET -LH	Distorted	48.00 FL	*48.00 FL
6	1		*REAR BUMPER SIDE GRILLE -LH	Dented	75.00 FL	*75.00 FL
7	1		*REAR BUMPER LOWER CHROME	Serviceable	335.00 FL	*- FL
8	1		*REAR BUMPER EXHAUST CHROME	Serviceable	330.00 FL	*- FL
9	1		*REAR BUMPER RADAR SENSOR -LH	Serviceable	1,220.00 FL	*- FL
10	1		*REAR BUMPER LOWER REINFORCEMENT	Repair	21.00 FL	*- FL
11	1		*REAR BUMPER CENTRE BRACKET	Serviceable	210.00 FL	*- FL
12	1		*REAR BUMPER SIDE BRACKET TAILLAMP -LH	Cracked	70.00 FL	*70.00 FL
13	1		*REAR BUMPER CENTRE CARRIER	Serviceable	85.00 FL	*- FL
14	10		*REAR BUMPER RIVETS	Necessary	60.00 FL	*60.00 FL
15	1		*LH REAR EXHAUST HEAT SHIELD	Dented	135.00 FL	*135.00 FL
16	1		*LH REAR EXHAUST MUFFLER	Repair	1,465.00 FL	*- FL
17	1		*REAR FENDER -LH	Bent	2,640.00 FL	*2,640.00 FL
18	1		*REAR FENDER INNER SHIELD -LH	Cracked	215.00 FL	*215.00 FL
19	8		*REAR FENDER INNER SHIELD CLIPS	Necessary	56.00 FL	*56.00 FL
20	1		*REAR WINDSCREEN GLASS MOULDING C/W GLASS	Not Necessary	1,475.00 FL	*- FL
21	1		*TAILLAMP -LH	Cracked	760.00 FL	*710.00 FL
22	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
23	1		*REAR WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
24	1		*REAR WINDSCREEN GLASS SOLAR FILM	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,259.00	6,233.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,181.90	617.30

Total Parts (\$\$)	11,077.10	5,615.70
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	1,200.00	700.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ROOF LINING SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	180.00	100.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
4	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	80.00	0.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	800.00	500.00
6	TO APPLY UNDERSEALING	New	80.00	30.00
7	TO FOCUS TAILLAMPS .TO CHECK REAR WIRING AND LIGHTING OPERATION	New	30.00	20.00
Gross Labour Cost (\$\$)			2,490.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >