

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22003865/UPA3Q2**Date:** 20/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02
Claimant Vehicle No : SNB4988Y **Insured Vehicle No :** GBF6286Y
 Date of Loss: 25/04/2022 Nature of Claim: TP Claim No: MFL2022D0002153

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB4988Y**
 Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMMU048847
 Reg. Date: 26/08/2021 (Man. Year: 2021) Chassis No: KMHLN41ETNU213555
 Colour: Red Odometer: 13693 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Hankook 8 mm Rear Left Side: Hankook 8 mm
 Front Right Side: Hankook 8 mm Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,407.90	10,498.00	12,909.90	55.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,740.00	3,060.00	2,680.00	46.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	29,147.90	13,558.00	15,589.90	53.49
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		15,065.45		
Global Sum Settlement (S\$)		15,000.00		

INSPECTION

Date of Assignment: 26/04/2022
 Date Inspected: 26/04/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
 Bukit
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2022)
Parts:	143	HYUNDAI CN7 AVANTE 1.6 DOHC CVT S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB4988Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	2,223.20 F	*2,023.20 FL
2	1		*BOOTLID REAR LOGO	Necessary	75.80 F	*26.10 FL
3	1		*BOOTLID AVANTE EMBLEM	Necessary	42.00 F	*42.00 FL
4	1		*BOOTLID S EMBLEM	Necessary	35.00 F	*35.00 FL
5	1		*BOOTLID REFLECTOR CENTRE	Cracked	1,162.20 F	*1,125.80 FL
6	1		*BOOTLID INNER LOCK	Bent	148.00 F	*148.00 FL
7	1		*BOOTLID LOCK SWITCH	Serviceable	101.40 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	166.00 F	*108.30 FL
9	1		*BOOTLID INNER TRIM	Torn	265.00 F	*120.80 FL
10	2		*BOOTLID HINGES	Repair	290.00 F	*- FL
11	1		*BOOTLID OUTER TOP GARNISH	Distorted / Cracked	1,125.80 F	*1,025.80 FL
12	1		*BOOTLID OUTER TOP GARNISH INNER BRACKET	Cracked	250.00 F	*225.00 FL
13	2		*BOOTLID OUTER TOP GARNISH INNER SIDE BRACKETS	Cracked	100.00 F	*100.00 FL
14	1		*BOOTLID OUTER TOP SPOILER INNR (BLACK)	Warped / Cracked	450.00 F	*397.00 FL
15	1		*SET BOOTLID REVERSE CAMERA	Shorted	745.00 F	*650.00 FL
16	1		*REAR BUMPER	Distorted	481.00 F	*470.80 FL
17	1		*REAR BUMPER LOWER	Distorted	440.60 F	*340.60 FL
18	1		*REAR BUMPER CENTRE LAMP	Cracked	280.00 F	*201.50 FL
19	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 F	*96.00 FL
20	2		*REAR BUMPER REFLECTORS	Cracked	116.40 F	*116.40 FL
21	1		*REAR BUMPER SPONGE	Not fitted	245.00 F	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Distorted	329.00 F	*294.80 FL
23	2		*REAR BUMPER REINFORCEMENT BRACKETS	Distorted	302.00 F	*210.00 FL
24	2		*REAR BUMPER REINFORCEMENT TOP BRACKETS	Cracked	50.00 F	*50.00 FL
25	1		*REAR BUMPER REINFORCEMENT LOWER BRACKETS (3 PCS)	Cracked (2 PCS ONLY)	75.00 F	*50.00 FL
26	4		*REAR BUMPER PDC SENSORS	Shorted (3 PCS ONLY)	676.80 F	*507.60 FL
27	1		*SET REAR BUMPER PDC SENSOR WIRE	Torn	236.10 F	*236.10 FL
28	1		*REAR BUMPER UNDER COVER	Distorted	68.00 F	*68.00 FL
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*40.00 FL
30	1		*REAR END PANEL	Badly Dented	537.00 F	*454.60 FL
31	1		*REAR END PANEL TOP GARNISH	Twisted	188.90 F	*95.50 FL
32	2		*TAILLAMPS	Cracked	1,318.00 F	*1,181.60 FL
33	2		*TAILLAMP HOUSING PANELS	Bent	500.00 F	*387.00 FL
34	1		*REAR EXHAUST	Repair	981.00 F	*- FL
35	1		*REAR EXHAUST HEAT SHIELD	Repair	145.00 F	*- FL
36	1		*REAR FLOOR PANEL	Repair	1,215.00 F	*- FL
37	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	355.00 F	*- FL
38	1		*REAR FLOOR PANEL SIDE MEMBER N/S	Repair	455.10 F	*- FL
39	1		*REAR CHASSIS MEMBER N/S	Not Necessary	845.20 F	*- FL
40	1		*REAR FENDER	Repair	1,915.10 F	*- FL
41	1		*REAR FENDER INNER TRIMS	N/S Not Necessary / O/S Torn	688.00 F	*208.00 FL
42	1		*REAR FENDER GLASS	Not Necessary	450.00 F	*- FL

Report was unsubmitted during this print-out.

3/20/23, 6:58 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR WINDSCREEN MOULDING	Not Necessary	85.30 F	*- FL
44	1		*REAR BLIND SPOT SENSOR UNIT	Cracked	1,850.00 F	*1,451.00 FL
45	1		*REAR BLIND SPOT SENSOR WIRE	Damaged	399.00 F	*355.00 FL
46	2		*REAR LICENCE PLATE LAMPS	Cracked	106.00 F	*106.00 FL
47	1		*REAR WINDSCREEN MOULDING	Not Necessary	165.00 F	*- FL
48	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
49	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
50	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
51	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
52	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
53	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	23,407.90 13,087.50
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00 2,589.50
					Total Parts (\$)	23,407.90 10,498.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	80.00
5	TO RESET & DIAGNOSTIC BLIND SPOT SENSOR ,CALIBRATION	New	500.00	300.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
7	TO DISMANTLE & REFIX FUEL TANK	New	80.00	0.00
8	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
9	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
10	TO SPRAY RUST PROOFING	New	180.00	80.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	1,200.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			5,740.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >