

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 1452X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID (CONSISTENT)	BENT	1,135.50	1,004.00
1	BOOT LID INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	280.60	-
1	BOOT LID EMBLEM -MAZDA (CONSISTENT)	NECESSARY	72.20	72.20
1	BOOT LID EMBLEM -SKYACTIVE (CONSISTENT)	NECESSARY	86.60	86.60
1	BOOT LID LOGO (CONSISTENT)	NECESSARY	71.50	71.50
1	BOOT LID HINGE (LH)(CONSISTENT)	NOT NECESSARY	115.50	-
1	BOOT LID HINGE (RH)(CONSISTENT)	NOT NECESSARY	115.50	-
1	BOOT LID LOCK(CONSISTENT)	NOT NECESSARY	180.70	-
1	BOOT LID WEATHERSTRIP (CONSISTENT)	NECESSARY	184.80	184.80
1	BOOT LID LAMP LH (CONSISTENT)	NOT NECESSARY	1,073.70	-
1	BOOT LID LAMP RH (CONSISTENT)	NOT NECESSARY	1,073.70	-
1	REAR BUMPER (CONSISTENT)	CUT	1,097.40	1,097.40
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	61.20	-
1	REAR BUMPER RETAINER RH(CONSISTENT)	NOT NECESSARY	61.20	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	638.30	541.70
1	REAR BUMPER TOWING COVER (LH)(CONSISTENT)	MISSING	27.50	27.50
1	REAR BUMPER TOWING COVER (RH)(CONSISTENT)	NOT NECESSARY	27.50	-
1	REAR BUMPER REFLECTOR (LH)(CONSISTENT)	NOT NECESSARY	61.10	-
1	REAR BUMPER REFLECTOR RH(CONSISTENT)	NOT NECESSARY	61.10	-
1	END PANEL (CONSISTENT)	BENT	701.10	557.00
1	END PANEL TOP GARNISH (CONSISTENT)	CRACKED	189.60	189.60
1	TAIL LAMP RH (CONSISTENT)	NOT NECESSARY	1,987.40	-
1	TAIL LAMP LH(CONSISTENT)	CRACKED	1,987.40	790.60
1	TAIL LAMP BRACKET (LH) (CONSISTENT)	NOT NECESSARY	325.90	-
1	TAIL LAMP BRACKET (RH)(CONSISTENT)	NOT NECESSARY	325.90	-
1	REAR FENDER INNER TRIM BOARD (LH)(CONSISTENT)	NOT NECESSARY	621.70	-
1	REAR FENDER INNER TRIM BOARD (RH)(CONSISTENT)	NOT NECESSARY	621.70	-
1	EXHAUT MUFFLER (CONSISTENT)	NOT NECESSARY	1,585.70	-
1	EXHAUT MUFFLER HEAT SHIELD (CONSISTENT)	NOT NECESSARY	79.50	-

Report Ref No. CC4/ASM22003867/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,970.30	-924.58
			11,881.20	3,698.32
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	30.00
	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	280.00	200.00
1	SET END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER PLATE WITH CASING (SN)(CONSISTENT)	NOT NECESSARY	60.00	-
			440.00	230.00
	<u>LABOUR</u>			
	TO DISMANTLE,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS.		1,000.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT .		1,200.00	600.00
	TO RUST PROOF AFFECTED AREA.		80.00	40.00
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR.		60.00	20.00
	DISMANTLE AND TRANSFER BOOT LID FITTINGS AND MECHANISM TO NEW BOOT LID /FACILITATE REPAIR .		120.00	60.00
	DISCONNECT AND CHECK ELECTRICAL WIRING ,HARNESS, WIRE SOCKET.		60.00	30.00
	REMOVE AND REPLACE REVERSE SENSOR .		80.00	60.00
	REMOVE AND REFIT END PANEL LINING AND GARNISH TO FACILITATE REPAIR.	NOT NECESSARY	80.00	-
	REMOVE AND REPLACE EXHAUST MUFFLER .	NOT NECESSARY	100.00	-
			2,780.00	1,410.00
	GRAND TOTAL		15,101.20	5,338.32
	RECOMMENDED COST OF LUMP SUM REPAIRS			4,250.00

Report Ref No. CC4/ASM22003867/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

(TO ITS PRE-ACCIDENT CONDITION)

Automotive Assessor

HO LEONG CHUAN
Automotive Assessor