



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 8188R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RR BUMPER (N)(CONSISTENT)	CRUSHED	591.60	591.60
	LESS 20% DISCOUNT		-118.32	-118.32
	ADDITIONAL LESS 20% DISCOUNT		-	-23.66
			473.28	449.62
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	COVER SENSOR BRACKET CENTER (SN)(CONSISTENT)	NECESSARY	156.60	156.60
1	COVER SENSOR BRACKET RH (SN)(CONSISTENT)	NECESSARY	103.90	103.90
1	COVER SENSOR BRACKET LH (SN)(CONSISTENT)	NECESSARY	103.90	103.90
1	SET SENSOR ASSY (SN)(CONSISTENT)	NOT NECESSARY	928.00	-
			1,292.40	364.40
	<b><u>LABOUR</u></b>			
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST.		110.00	110.00
	REPAIR/REPLACE REAR BUMPER & END PANEL.		500.00	250.00
	RESPRAY REAR BUMPER & END PANEL.		400.00	200.00
	ADDITIONAL LESS 5% DISCOUNT		-	-28.00
			1,130.00	532.00
<b>GRAND TOTAL</b>			<b>2,895.68</b>	<b>1,346.02</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,346.02</b>

Report Ref No. CC4/ASM22003869/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.