

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22003874/ETY3E2

Date: 30/05/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21P00152400
Claimant Vehicle No : SMB3533U Insured Vehicle No : SMV1851J
Date of Loss: 24/04/2022 Nature of Claim: TP Claim No: DMPC2200168H/02/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB3533U**
Make & Model: ALEXANDER DENNIS ENVIRO500, 8.8 D (A) Engine No: 22119798
Reg. Date: 01/09/2014 (Man. Year: 2014) Chassis No: SFD76CLR5EMTL3462
Colour: Multi-colour Odometer: 476887 km
Engine Capacity: 8849 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5(D)
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5/5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	290.33	261.30	29.03	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	965.00	1,625.00	62.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,880.33	1,226.30	1,654.03	57.43
+ GST 7.00/7.00% (S\$)	201.62	85.84	115.78	57.42
Nett Amount (S\$)	3,081.95	1,312.14	1,769.81	57.43

INSPECTION

Date of Assignment: 26/04/2022
Date Inspected: 26/04/2022 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170
Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,226.29

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 May 2022)	
Parts:	N/A	ALEXANDER DENNIS ENVIRO500 8.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3533U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*QUARTER WINDOW GLASS RH	Broken	258.33 F	*258.33 FL
2	1		*SIKAFLEX BLACK	Necessary	32.00 F	*32.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					290.33	290.33
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	29.03
Total Parts (S\$)					290.33	261.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE : - ITEM NOS. 1-2	New	650.00	325.00
2	TO REMOVE INSTALL PARTS AND TO PERFORM REPAIR WORKS : - FRONT RH CORNER BUMPER	New	1,300.00	0.00
3	SPRAY PAINTING : - FRONT RH CORNER BUMPER	New	640.00	640.00
Gross Labour Cost (\$)			2,590.00	965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >