

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22003876/KPA3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100418389
<b>Claimant Vehicle No :</b>	SKX6486K	<b>Insured Vehicle No :</b>	SKT9281K
Date of Loss:	26/04/2022	Nature of Claim:	TP
		Claim No:	0780359530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKX6486K</b>	Engine No:	L13A54003534
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGD18507S232422
Reg. Date:	22/11/2007 (Man. Year: 2007)	Odometer:	180869 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	HIFLY 3 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	HIFLY 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>2,600.00</b>	<b>-2,600.00</b>	
<b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b>		420.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>+ Other Costs (S\$)</b>		50.00		
<b>Nett Liability (S\$)</b>		<b>3,072.00</b>		

INSPECTION

Date of Assignment:	28/04/2022	
Date Inspected:	28/04/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	0.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$5,000.00

LTA REIMBURSEMENT VALUE (RV) : \$2,400.00

NETT VALUE : \$2,600.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >