

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22003882/KEA3Q2
Date: 22/11/2022

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 7210082213 |
| Claimant Vehicle No : | SND8782L | Insured Vehicle No : | SDA8131A |
| Date of Loss: | 22/04/2022 | Nature of Claim: | TP |
| | | Claim No: | 9523345496SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No: | SND8782L | Engine No: | L15Z1002979 |
| Make & Model: | HONDA VEZEL, 1.5 G CVT (A) | Chassis No: | RV31002425 |
| Reg. Date: | 28/01/2022 (Man. Year: 2021) | Odometer: | 6983 km |
| Colour: | Metallic Grey | | |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/60 R16 | Rear Tyre Size: | 215/60 R16 |
| Front Left Side: | Dunlop 9 mm | Rear Left Side: | Dunlop 9 mm |
| Front Right Side: | Dunlop 9 mm | Rear Right Side: | Dunlop 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 6,268.00 | 3,546.94 | 2,721.06 | 43.41 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,120.00 | 1,090.00 | 1,030.00 | 48.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 8,388.00 | 4,636.94 | 3,751.06 | 44.72 |
| + GST 7.00/7.00% (\$\$) | 587.16 | 324.59 | 262.57 | 44.72 |
| Nett Amount (\$\$) | 8,975.16 | 4,961.53 | 4,013.63 | 44.72 |
| + Loss of Use (4.0 x S\$60.00/day) (\$\$) | | 240.00 | | |
| + Doc/Search Fee (\$\$) | | 7.45 | | |
| Nett Liability (\$\$) | | 5,208.98 | | |
| Global Sum Settlement (\$\$) | | 5,200.00 | | |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 26/04/2022 | |
| Date Inspected: | 26/04/2022 | Inspected At: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143 |
| Estimated Period of Repair: | 4.0 days | |

11/22/22, 11:25 AM

Adjuster Report

Adjuster: KENNETH KONG

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Bent | 1,440.00 FL | *1,203.50 FL |
| 2 | 1 | | *REAR TAILGATE VEZEL EMBLEM | Necessary | 60.00 FL | *60.00 FL |
| 3 | 1 | | *REAR TAILGATE INNER LOCK | Repair | 352.00 FL | *- FL |
| 4 | 1 | | *REAR TAILGATE INNER TRIM BOARD | Serviceable | 226.00 FL | *- FL |
| 5 | 1 | | *REAR TAILGATE WEATHERSTRIP | Serviceable | 162.00 FL | *- FL |
| 6 | 1 | | *REAR WINDSCREEN MOULDING | Necessary | 150.00 FL | *150.00 FL |
| 7 | 1 | | *REAR BUMPER | Buckled | 1,480.00 FS | *1,230.50 FS |
| 8 | 1 | | *REAR BUMPER SIDE BRACKET LH | Serviceable | 39.00 FL | *- FL |
| 9 | 1 | | *REAR BUMPER SIDE BRACKET RH | Serviceable | 39.00 FL | *- FL |
| 10 | 1 | | *REAR BUMPER REFLECTOR LH | Cracked | 54.00 FL | *54.00 FL |
| 11 | 1 | | *REAR BUMPER LOWER DIFFUSER WITH GARNISH COVER | Dented / Distorted | 1,053.00 FL | *825.30 FL |
| 12 | 2 | | *REAR BUMPER REVERSE SENSOR | Dented (1 PCS ONLY) | 1,080.00 FL | *331.00 FL |
| 13 | 1 | | *REAR END PANEL UPPER COVER | Serviceable | 117.00 FL | *- FL |
| 14 | 1 | | *REAR END PANEL | Repair | 685.00 FL | *- FL |
| 15 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 16 | 1 | | *REAR TAILGATE INNER TRIMBOARD CLIPS | Not Necessary | 40.00 FS | *- FS |
| 17 | 1 | | *REAR BUMPER CLIPS | Necessary | 50.00 FS | *50.00 FS |
| 18 | 1 | | *REAR END PANEL SEALANT | Not Necessary | 80.00 FS | *- FS |
| 19 | 1 | | *REAR END PANEL UPPER COER CLIPS | Not Necessary | 40.00 FS | *- FS |
| 20 | 1 | | *REAR NUMBER PLATE & HOLDER | Cracked | 50.00 FS | *45.00 FS |
| 21 | 1 | | *REAR KEY ANTENNA SENSOR | Cracked | 103.00 FL | *103.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 7,380.00 | 4,092.30 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,112.00 | 545.36 |
| Total Parts (\$\$) | 6,268.00 | 3,546.94 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC | New | 700.00 | 400.00 |
| 2 | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC | New | 700.00 | 400.00 |
| 3 | LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT REAR WINDSCREEN MOULDING TO EFFECT REPLACE OF REAR TAILGATE | New | 150.00 | 120.00 |
| 4 | LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS | New | 120.00 | 60.00 |
| 5 | LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC | New | 100.00 | 60.00 |
| 6 | TO TUFF-KOTE & UNDERSEAL MATERIALS | New | 120.00 | 30.00 |
| 7 | TO DIAGNOSIS FAULT CODE & RESET MEMORY | New | 150.00 | 0.00 |
| 8 | TO CHECK WIRING & CENTRAL LOCKING SYSTEM | New | 80.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 2,120.00 | 1,090.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >