



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 24U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEAD LAMP RH	CUT	2,689.10	725.00
1	FRONT LOWER GRILLE	NOT NECESSARY	689.51	-
1	FRONT BUMPER	DISTORTED	849.80	654.00
2	FRONT BUMPER SIDE RETAINER LH / RH @\$103.40 EACH	NOT NECESSARY	206.80	-
1	FRONT BUMPER FOG LAMP GARNISH RH	NOT NECESSARY	499.60	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	69.80	-
1	WIREHARNESH HOUSING RH	NOT NECESSARY	789.94	-
1	FRONT WHEEL BEARING & HUB ASSY RH	NOT NECESSARY	628.10	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	984.90	-
1	FRONT LOWER ARM RH	NOT NECESSARY	682.51	-
1	FRONT ABSORBER RH	NOT NECESSARY	601.92	-
1	FRONT STABILIZER LINKAGE RH	NOT NECESSARY	210.40	-
1	FRONT STABILIZER BAR	NOT NECESSARY	410.92	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	2,191.27	-
	LESS 25% DISCOUNT		-2,876.14	-344.75
			8,628.43	1,034.25
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE & GARNISH (SN)	NOT NECESSARY	200.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	15.00
1	FRONT BUMPER LOWER LID (SN)	NOT NECESSARY	2,000.00	-
1	FRONT DOOR ARC GARNISH (SN)	TO REPAIR SEE LABOUR	1,000.00	-
			3,250.00	15.00
<u>LABOUR</u>				
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH & FRONT DOOR ARC GARNISH.		2,000.00	300.00
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS.		2,000.00	400.00
	TO TUFF COAT DAMAGED AREAS.		200.00	15.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS.	NOT NECESSARY	400.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS.	NOT NECESSARY	200.00	-
	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS.	NOT NECESSARY	300.00	-
			5,220.00	715.00
GRAND TOTAL			17,098.43	1,764.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/SMR22003883/Dny3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.