

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22003885/APA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MCV0007531
Claimant Vehicle No :	SLV9447C	Insured Vehicle No :	GBB6803B
Date of Loss:	25/04/2022	Nature of Claim:	TP
		Claim No:	MCV2022D0002171

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9447C	Engine No:	L15B4430446
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11230443
Reg. Date:	23/01/2018 (Man. Year: 2017)	Odometer:	70699 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,907.24	4,667.04	2,240.20	32.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,510.00	710.00	31.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,127.24	6,177.04	2,950.20	32.32
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	9,127.24	4,900.00	4,227.24	46.31
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,335.45		

INSPECTION

Date of Assignment:	26/04/2022	
Date Inspected:	26/04/2022	Inspected At: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV9447C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	1,300.00 FL	*1,100.00 FL
2	2		*TAIL GATE ABSORBER	Not Necessary	470.40 FL	*- FL
3	1		*TAIL GATE HINGES	Not Necessary	136.00 FL	*- FL
4	1		*TAIL GATE WEATHERSTRIP	Not Necessary	185.20 FL	*- FL
5	1		*TAIL GATE HONDA LOGO	Necessary	55.60 FL	*55.60 FL
6	1		*TAIL GATE VEZELEMBLEM	Necessary	57.60 FL	*57.60 FL
7	1		*TAIL GATE REFLECTOR RH	Cut	290.70 FL	*290.70 FL
8	1		*TAIL GATE REFLECTOR LH	Cut	290.70 FL	*290.70 FL
9	1		*TAIL GATE LOCK	Damaged	180.40 FL	*180.40 FL
10	1		*TAIL GATE LOWER CATCH	Not Necessary	42.00 FL	*- FL
11	1		*TAIL GATE TRIMBOARD	Cut	246.00 FL	*246.00 FL
12	4		*REAR WINDSCREEN GLASS MOULDING	Necessary	301.60 FL	*301.60 FL
13	1		*REAR WINDSCREEN	Shattered	1,080.00 FL	*1,080.00 FL
14	1		*REAR BUMPER	Deformed	963.20 FL	*745.00 FL
15	1		*REAR BUMPER SIDE RETAINER RH	Necessary	33.60 FL	*33.60 FL
16	1		*REAR BUMPER SIDE RETAINER LH	Necessary	33.60 FL	*33.60 FL
17	1		*REAR BUMPER REFLECTOR LH	Not Necessary	151.20 FL	*- FL
18	1		*REAR BUMPER CENTRE GUARD CHROME	Bent	250.00 FL	*250.00 FL
19	1		*REAR BUMPER PAD (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*REAR BUMPER PAD CENTRE CHROME	Cut	280.00 FL	*280.00 FL
21	1		*REAR END PANEL	Repair	530.80 FL	*- FL
22	1		*REAR END PANEL GARNISH	Cut	114.00 FL	*114.00 FL
23	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*SPARE TYRE BOARD	Not Necessary	450.20 FL	*- FL
25	1		*TOOLS FOAM (NPA)	Not Necessary	0.00 FL	*- FL
26	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
27	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
28	1		*SEALANT	Not Necessary	60.00 FS	*- FS
29	1		*REAR END PANEL GARNISH CLIP (7 PCS)	Necessary	35.00 FS	*10.00 FS
30	1		*REAR NUMBER PLATE W/CASING	Not Necessary	70.00 FS	*- FS
31	1		*REAR CAMERA	Damaged	488.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,395.80	5,678.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,488.56	1,011.76
Total Parts (\$)	6,907.24	4,667.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	600.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	600.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	60.00	40.00
5	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
6	TO CLEAN SHATTERED GLASS	New	100.00	60.00
7	TO REMOVE AND REFIT REAR SEATS ,REAR WHEELHOUSE INNER GARNISH ,FLOOR CARPET UPHOLSTERY TO FACILITATE REPAIRS	New	250.00	60.00
Gross Labour Cost (\$)			2,220.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >