

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003887/AQY3Q2**Date:** 27/09/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00259992100		
Claimant Vehicle No :	SMP6165E	Insured Vehicle No :	SLD72D		
Date of Loss:	25/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202779/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6165E		Engine No:	1ZR0E02306
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)		Chassis No:	MR053REH604598611
Reg. Date:	04/10/2019 (Man. Year: 2019)		Odometer:	78493 km
Colour:	Brown			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,041.80	3,589.77	2,452.03	40.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,590.00	980.00	38.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,611.80	5,179.77	3,432.03	39.85
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	8,611.80	4,000.00	4,611.80	53.55
+ GST 7.00/7.00% (S\$)	602.83	280.00	322.83	53.55
Nett Amount (S\$)	9,214.63	4,280.00	4,934.63	53.55

INSPECTION

Date of Assignment:	28/04/2022	
Date Inspected:	04/05/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6165E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PETROL LID COVER RIVET	Not Necessary	7.60 FL	*- FL
2	1		*REAR BUMPER	Torn	556.40 FL	*556.40 FL
3	1		*REAR BUMPER LH END SEAL COVER	Not Necessary	55.10 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER L/R	O/S Cracked	218.60 FL	*109.30 FL
5	1		*REAR LH BEARING HUB	Damaged	960.50 FL	*762.00 FL
6	1		*REAR LH DOOR	Dented	1,248.50 FL	*1,248.50 FL
7	1		*REAR LH DOOR FRAME BLACK STICKER	Necessary	43.50 FL	*43.50 FL
8	1		*REAR LH DOOR INNER PLASTIC SEAL COVER	Not Necessary	33.20 FL	*- FL
9	1		*REAR LH DOOR RUBBER GUIDE STOPPER	Not Necessary	10.50 FL	*- FL
10	1		*REAR LH DOOR VERTICAL GARNISH	Not Necessary	93.00 FL	*- FL
11	1		*REAR LH DOOR WEATHER STRIP	Not Necessary	155.00 FL	*- FL
12	1		*REAR LH FENDER	Repair	1,149.00 FL	*- FL
13	1		*REAR LH SPORT RIM	Cut	1,642.80 FS	*1,400.00 FS
14	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	41.10 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*SET REAR BUMPER LH END SEAL COVER CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*SET REAR LH DOOR CHROME MOULDING	Not Necessary	80.00 FS	*- FS
18	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*SET REAR LH DOOR VISOR GARNISH	Necessary	250.00 FS	*120.00 FS
20	1		*REAR LH TYRE	Not Necessary	450.00 FS	*- FS
21	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,184.80	4,269.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,143.00	679.93
Total Parts (\$\$)	6,041.80	3,589.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE AND REFIT REAR WINDSCREEN (TO FR)	New	150.00	0.00
3	TO REMOVE ,REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR)	New	150.00	80.00
4	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
5	TO REMOVE ,REINSTALL PETROL TANK (TO FR)	New	80.00	0.00
6	TO REMOVE REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	40.00
7	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	80.00
8	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	850.00	600.00
9	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	600.00
10	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	50.00
Gross Labour Cost (S\$)			2,570.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >