

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003889/ATY3N2**Date:** 23/05/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00011622203

**Claimant Vehicle No :** SLP5632S **Insured Vehicle No :** GBE6157S

Date of Loss: 22/04/2022 Nature of Claim: TP Claim No: SNM22D202778/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP5632S**

Make & Model: SUBARU FORESTER, 2.0 (A) Engine No: FA20B989871

Reg. Date: 09/06/2017 (Man. Year: 2017) Chassis No: JF1SJGK85HG088926

Colour: Grey Odometer: 103184 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,283.00	3,807.20	1,475.80	27.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,310.00	1,200.00	47.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,793.00</b>	<b>5,117.20</b>	<b>2,675.80</b>	<b>34.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>(S\$)</b>	7,793.00	4,000.00	3,793.00	48.67
<b>+ GST 7.00/7.00% (S\$)</b>	545.51	280.00	265.51	48.67
<b>Nett Amount (S\$)</b>	<b>8,338.51</b>	<b>4,280.00</b>	<b>4,058.51</b>	<b>48.67</b>

INSPECTION

Date of Assignment: 26/04/2022

Date Inspected: 26/04/2022 Inspected At: N-51 AUTOMOTIVE PL  
2 KAKI BUKIT AVE 2  
#01-17 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
<b>Parts:</b> M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP5632S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	640.30 FL	*640.30 FL
2	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	105.60 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	420.90 FL	*420.90 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	32.60 FL	*32.60 FL
5	1		*REAR BUMPER TOP GARNISH	Deformed	330.20 FL	*330.20 FL
6	1		*REAR BUMPER TOW HOOK COVER	Deformed	24.30 FL	*24.30 FL
7	1		*REAR END PANEL	Not Necessary	320.40 FL	*- FL
8	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	60.90 FL	*- FL
9	1		*REAR TAILGATE	Dented	1,072.00 FL	*1,072.00 FL
10	1		*REAR TAILGATE AWD EMBLEM	Necessary	48.00 FL	*48.00 FL
11	1		*REAR TAILGATE FORESTER EMBLEM	Necessary	72.40 FL	*72.40 FL
12	1		*REAR TAILGATE LOGO EMBLEM	Necessary	88.40 FL	*88.40 FL
13	1		*REAR TAILGATE SUBARU EMBLEM	Necessary	72.40 FL	*72.40 FL
14	1		*REAR TAILGATE XT EMBLEM	Necessary	35.00 FL	*35.00 FL
15	2		*REAR TAILGATE HINGES L/R	Not Necessary	114.60 FL	*- FL
16	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	19.60 FL	*- FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	180.40 FL	*180.40 FL
18	1		*REAR TAILGATE MECHANISM LOCK	Damaged	560.90 FL	*395.00 FL
19	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	68.60 FL	*- FL
20	1		*REAR TAILGATE OUTER GARNISH	Cracked	248.70 FL	*248.70 FL
21	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	120.40 FL	*- FL
22	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	149.80 FL	*149.80 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
25	1		*REAR TAILGATE CAMERA	Damaged	800.00 FS	*380.00 FS
26	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
28	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
30	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
31	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	48.60 FL	*48.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,250.00</b>	<b>4,579.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	967.00	771.80
<b>Total Parts (\$\$)</b>	<b>5,283.00</b>	<b>3,807.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
5	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
7	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,510.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >