



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 1368A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (SN)	DENTED	1,530.36	1,530.36
1	LH/REAR BUMPER CHROME MOULDING (SN)	NECESSARY	149.15	149.15
1	RH/REAR BUMPER CHROME MOULDING (SN)	NECESSARY	149.15	149.15
1	REAR LOWER BLACK TRIM BUMPER (SN)	BROKEN	329.97	329.97
1	REAR BUMPER CHROME MOULDING (SN)	BROKEN	355.64	355.64
12	RIVET @ \$4.81 (SN)	NECESSARY	57.72	57.72
1	CTR/BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	131.66	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	925.24	-
1	LH/BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	81.14	-
1	RH/BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	79.57	-
			3,789.60	2,571.99
<b><u>LABOUR</u></b>				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			1,440.00	960.00
RESPRAY REAR BUMPER.			960.00	800.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.			380.00	380.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.			120.00	120.00
			2,900.00	2,260.00
<b>GRAND TOTAL</b>			<b>6,689.60</b>	<b>4,831.99</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,831.99</b>

Report Ref No. CS/FCI22003890/Evy3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.