

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 8423P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	787.61	787.61
1	REAR BUMPER LOWER	CUT	213.33	213.33
1	COVER REAR BUMPER (BLACK)	NOT NECESSARY	198.19	-
1	RETAINER S.S ULTRASONIC	NECESSARY	108.88	108.88
1	COVER TOWING HOOK REAR	NOT NECESSARY	49.98	-
1	BRACKET RH REAR BUMPER	NOT NECESSARY	188.56	-
1	BRACKET LH REAR BUMPER	BROKEN	188.56	188.56
1	WHEEL ARCH REAR RH	CUT	151.32	151.32
4	CLIP	NECESSARY	8.84	8.84
4	CLIP	NECESSARY	5.72	5.72
1	SENSOR ULTRASONIC SIDE	NOT NECESSARY	498.10	-
4	GASKET SENSOR ULTRASONIC	NECESSARY	26.80	26.80
1	TAIL LAMP REAR RH	BROKEN	518.18	518.18
1	CHROME RING RH TAILLAMP	CUT	59.41	59.41
1	CHROME RING LH TAILLAMP	NOT NECESSARY	59.41	-
			3,062.89	2,068.65
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER. TO REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.		2,100.00	1,260.00
	TO RESPRAY REAR BUMPER AND REAR FENDER RH.		1,800.00	1,600.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO TRANSFER / SUPPLY THE REVERSE SENSORS.		500.00	180.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
			5,250.00	3,590.00
	GRAND TOTAL		8,362.89	5,678.65

Report Ref No. CS/SMR22003891/Eny3e2





RECOMMENDED COST OF REPAIRS			5,678.65	
-----------------------------	--	--	----------	--

Report Ref No. CS/SMR22003891/Eny3e2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator