



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 3623C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DENTED	789.60	689.00
1	FRONT BUMPER REINFORCEMENT	BENT	397.90	310.00
1	FRONT BUMPER FOG LAMP GARNISH RH	NO SUCH PARTS	186.60	-
1	FRONT BUMPER LOWER GRILLE	BROKEN	298.60	194.60
1	FRONT BUMPER LICENSE PLATE	MISSING	78.00	60.00
1	FRONT GRILLE	CRACKED	381.70	224.60
1	FRONT GRILLE LOGO	NECESSARY	87.00	34.00
1	FRONT SUPPORT PANEL	NOT DAMAGED	798.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT DAMAGED	185.60	-
1	HEADLAMP ASSY	BROKEN	878.60	633.20
1	HEADLAMP LOWER BRACKET	NOT DAMAGED	188.90	-
	LESS 20% DISCOUNT		-854.10	-429.08
			3,416.40	1,716.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$84.00 (SN)	NECESSARY	168.00	102.00
1	FRONT BUMPER LOWER LIP (FIBRE)(SN)	CRACKED	850.00	600.00
1	FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT SUPPORT PANEL SEALANT (SN)	NOT DAMAGED	100.00	-
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT DAMAGED	50.00	-
1	FRONT NUMBER PLATE W/CASING (SN)	MISSING	80.00	80.00
			1,478.00	842.00
<b><u>LABOUR</u></b>				
	CHECK WIRING.	NOT NECESSARY	100.00	-
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	PANEL BEATING.		1,000.00	600.00
	RUST PROOFING.	NOT NECESSARY	200.00	-

Report Ref No. CS/AGI22003893/Bty3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,000.00	200.00
			2,600.00	800.00
GRAND TOTAL			7,494.40	3,358.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/AGI22003893/Bty3n2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.