

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003894/VQY3M4**Date:** 04/08/2022**REFERENCE**

|                              |                                               |                             |                    |                                   |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00011012205 |                                   |
| <b>Claimant Vehicle No :</b> | SKS7177Y                                      | <b>Insured Vehicle No :</b> | GBB7529L           |                                   |
| Date of Loss:                | 19/04/2022                                    | Nature of Claim:            | TP                 | Claim No: SNM22D202688/C02/CHEESC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |  |             |                   |
|-----------------------------|-----------------------------------|--|-------------|-------------------|
| Reg No:                     | <b>SKS7177Y</b>                   |  | Engine No:  | B4204T111955437   |
| Make & Model:               | VOLVO XC60, 2.0 T5 (A)            |  | Chassis No: | YV1DZ40LDH2128262 |
| Reg. Date:                  | 28/04/2017 (Man. Year: 2017)      |  | Odometer:   | 106451 km         |
| Colour:                     | Grey                              |  |             |                   |
| Engine Capacity:            | 1969 cc                           |  |             |                   |
| Market Value/New Car Price: | N/A                               |  |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |  |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 265/40 R21   | Rear Tyre Size:  | 265/40 R21   |
| Front Left Side:  | Pirelli 7 mm | Rear Left Side:  | Pirelli 7 mm |
| Front Right Side: | Pirelli 7 mm | Rear Right Side: | Pirelli 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 16,542.62         | 8,225.98          | 8,316.64          | 50.27         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 4,880.00          | 1,640.00          | 3,240.00          | 66.39         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>21,422.62</b>  | <b>9,865.98</b>   | <b>11,556.64</b>  | <b>53.95</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>7,850.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>21,422.62</b>  | <b>7,850.00</b>   | <b>13,572.62</b>  | <b>63.36</b>  |

**INSPECTION**

|                             |            |               |                                                                               |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------|
| Date of Assignment:         | 24/06/2022 |               |                                                                               |
| Date Inspected:             | 27/04/2022 | Inspected At: | JEW Motors (HQ)<br>60 Jalan Lam Huat Carros Centre #03-72<br>Singapore 737869 |
| Estimated Period of Repair: | 5.0 days   |               |                                                                               |

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 04 Aug 2022)           |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKS7177Y)                                                                                                                                    |                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR TAILGATE                          | Cracked       | 3,185.30 FL | *2,780.00 FL |
| 2   | 1   |          | *REAR TAILGATE VOLVO EMBLEM             | Necessary     | 106.40 FL   | *106.40 FL   |
| 3   | 1   |          | *REAR TAILGATE XC 60 EMBLEM             | Necessary     | 121.50 FL   | *121.50 FL   |
| 4   | 1   |          | *REAR TAILGATE T5 EMBLEM                | Necessary     | 101.80 FL   | *101.80 FL   |
| 5   | 1   |          | *REAR TAILGATE CHROME MOULDING          | Scratched     | 227.10 FL   | *227.10 FL   |
| 6   | 1   |          | *REAR TAILGATE LOCK                     | Serviceable   | 687.10 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER COVER                      | Bent          | 2,392.10 FL | *1,600.00 FL |
| 8   | 1   |          | *REAR BUMPER SPOILER                    | Bent          | 562.20 FL   | *562.20 FL   |
| 9   | 1   |          | *REAR BUMPER MOULDING                   | Necessary     | 246.60 FL   | *246.60 FL   |
| 10  | 1   |          | *TAILPIPE BRACKET RH                    | Serviceable   | 54.20 FL    | *- FL        |
| 11  | 1   |          | *TAILPIPE BRACKET LH                    | Cut           | 54.20 FL    | *54.20 FL    |
| 12  | 1   |          | *REAR BUMPER EXHAUST CHROME PLATE RH    | Serviceable   | 308.20 FL   | *- FL        |
| 13  | 1   |          | *REAR BUMPER EXHAUST CHROME PLATE LH    | Scratched     | 308.20 FL   | *308.20 FL   |
| 14  | 1   |          | *PROTECTING PLATE                       | Dented        | 1,174.40 FL | *770.00 FL   |
| 15  | 10  |          | *REAR BUMPER CLIPS                      | Necessary     | 83.00 FL    | *83.00 FL    |
| 16  | 10  |          | *BLIND RIVET                            | Necessary     | 41.00 FL    | *41.00 FL    |
| 17  | 1   |          | *PARK HOLDER KIT                        | Necessary     | 34.60 FL    | *34.60 FL    |
| 18  | 10  |          | *PLASTIC RIVET                          | Necessary     | 85.00 FL    | *85.00 FL    |
| 19  | 1   |          | *REAR BUMPER REFLECTOR LAMP RH          | Serviceable   | 118.30 FL   | *- FL        |
| 20  | 1   |          | *REAR BUMPER REFLECTOR LAMP LH          | Cracked       | 118.30 FL   | *118.30 FL   |
| 21  | 4   |          | *REAR BUMPER PARKING SENSOR             | Cut           | 897.20 FL   | *600.00 FL   |
| 22  | 1   |          | *REAR BUMPER REINFORCEMENT              | Dented        | 1,022.30 FL | *1,022.30 FL |
| 23  | 1   |          | *REAR BUMPER CENTRE BRACKET             | Serviceable   | 283.00 FL   | *- FL        |
| 24  | 1   |          | *REAR BUMPER TOW COVER                  | Serviceable   | 73.90 FL    | *- FL        |
| 25  | 1   |          | *REAR TAILLAMP ASSEMBLY RH              | Serviceable   | 710.90 FL   | *- FL        |
| 26  | 1   |          | *REAR TAILLAMP ASSEMBLY LH              | Serviceable   | 710.90 FL   | *- FL        |
| 27  | 1   |          | *REAR END PANEL                         | Repair        | 788.75 FL   | *- FL        |
| 28  | 1   |          | *REAR END PANEL TOP GARNISH             | Serviceable   | 310.10 FL   | *- FL        |
| 29  | 1   |          | *REAR EXHAUST PIPE                      | Repair        | 1,850.90 FL | *- FL        |
| 30  | 2   |          | *REAR EXHAUST PIPE MOUNTING             | Serviceable   | 110.00 FL   | *- FL        |
| 31  | 1   |          | *REAR EXHAUST HEAT SHIELD               | Serviceable   | 268.80 FL   | *- FL        |
| 32  | 1   |          | *REAR NUMBER PLATE                      | Serviceable   | 50.00 FS    | *- FS        |
| 33  | 1   |          | *SET REAR TAILLAMP ASSEMBLY CLIPS       | Necessary     | 50.00 FS    | *30.00 FS    |
| 34  | 1   |          | *SET REAR BOOTLID INNER TRIM CLIPS      | Necessary     | 40.00 FS    | *20.00 FS    |
| 35  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS   | Necessary     | 50.00 FS    | *30.00 FS    |
| 36  | 1   |          | *REAR TAILGATE WINDSCREEN GLASS SEALANT | Necessary     | 200.00 FS   | *100.00 FS   |
| 37  | 1   |          | *REAR BOOTLID SEALANT                   | Necessary     | 150.00 FS   | *70.00 FS    |
| 38  | 1   |          | *REAR END PANEL SEALANT                 | Not Necessary | 120.00 FS   | *- FS        |
| 39  | 1   |          | *REAR TAILGATE REVERSE CAMERA           | Serviceable   | 550.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>18,246.25</b> | <b>9,112.20</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 1,703.63         | 886.22          |
| <b>Total Parts (\$\$)</b>                                  | <b>16,542.62</b> | <b>8,225.98</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                          |          |                 |                 |
| 1                               | TO PANEL BEAT, REMOVE & REFIX PARTS                                      | New      | 1,600.00        | 600.00          |
| 2                               | TO SPRAY PAINT AFFECTED AREAS                                            | New      | 1,600.00        | 600.00          |
| 3                               | WIRING & BULB CHECK                                                      | New      | 100.00          | 30.00           |
| 4                               | TO TRANSFER REAR TAILGATE MECHANISM                                      | New      | 150.00          | 70.00           |
| 5                               | TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS                         | New      | 150.00          | 120.00          |
| 6                               | TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR                             | New      | 120.00          | 30.00           |
| 7                               | TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA                           | New      | 150.00          | 30.00           |
| 8                               | TO REMOVE & REFIX REAR EXHAUST PIPE                                      | New      | 120.00          | 70.00           |
| 9                               | TO APPLY ANTI RUST ON AFFECTED PARTS                                     | New      | 100.00          | 30.00           |
| 10                              | TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS               | New      | 150.00          | 0.00            |
| 11                              | TO CONDUCT WATER LEAK TEST                                               | New      | 100.00          | 0.00            |
| 12                              | TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION | New      | 540.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                          |          | <b>4,880.00</b> | <b>1,640.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >