

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003899/BQY3Q2
Date: 18/11/2022

REFERENCE

| | | | |
|-----------------------|---|----------------------|------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00101882103 |
| Claimant Vehicle No : | SKM737J | Insured Vehicle No : | GBG5184J |
| Date of Loss: | 24/04/2022 | Nature of Claim: | TP |
| | | Claim No: | SNM22D202804/C02/TANKW |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SKM737J | Engine No: | R18A14002288 |
| Make & Model: | HONDA CIVIC, 1.8 L 5AT (A) | Chassis No: | JHMFD16309S200252 |
| Reg. Date: | 05/11/2008 (Man. Year: 2008) | Odometer: | 0 km |
| Colour: | Black | | |
| Engine Capacity: | 1799 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/40 R18 | Rear Tyre Size: | 225/40 R18 |
| Front Left Side: | Michelin 5 mm | Rear Left Side: | Michelin 5 mm |
| Front Right Side: | Michelin 5 mm | Rear Right Side: | Michelin 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|-----------------|--------------|
| Parts | 7,651.44 | 2,249.36 | 5,402.08 | 70.60 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,750.00 | 800.00 | 1,950.00 | 70.91 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 10,401.44 | 3,049.36 | 7,352.08 | 70.68 |
| Approved Total (Overridden) (\$\$) | | 2,100.00 | | |
| | 10,401.44 | 2,100.00 | 8,301.44 | 79.81 |
| + GST 7.00/7.00% (\$\$) | 728.10 | 147.00 | 581.10 | 79.81 |
| Nett Amount (\$\$) | 11,129.54 | 2,247.00 | 8,882.54 | 79.81 |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 26/04/2022 | |
| Date Inspected: | 27/04/2022 | Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 17 Nov 2022) |
| Parts: | 143 | HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKM737J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------|-------------|------------|
| 1 | 1 | | *FRONT BUMPER RH SIDE RETAINER | Necessary | 33.80 FL | *26.80 FL |
| 2 | 1 | | *FRONT BUMPER LH SIDE RETAINER | Necessary | 33.80 FL | *26.80 FL |
| 3 | 1 | | *RH HEADLAMP ASSY | Broken | 713.50 FL | *633.20 FL |
| 4 | 1 | | *RH HEADLAMP LOWER BRACKET | Not Damaged | 55.30 FL | *- FL |
| 5 | 1 | | *LH FRONT FENDER | Dented | 789.90 FL | *587.40 FL |
| 6 | 1 | | *LH FRONT FENDER SPLASH SHIELD | Not Damaged | 79.50 FL | *- FL |
| 7 | 1 | | *SET LH FRONT FENDER SPLASH SHIELD CLIPS | Not Damaged | 50.00 FL | *- FL |
| 8 | 1 | | *LH FRONT FENDER QUARTER GLASS WITH RUBBER SEAL | Not Damaged | 245.60 FL | *- FL |
| 9 | 1 | | *LH FRONT LOWER ARM | Not Damaged | 338.50 FL | *- FL |
| 10 | 1 | | *LH FRONT KNUCKLE ARM | Not Damaged | 355.70 FL | *- FL |
| 11 | 1 | | *LH FRONT WHEEL BEARING | Not Damaged | 167.40 FL | *- FL |
| 12 | 1 | | *LH FRONT SHOCK ABSORBER | Not Damaged | 398.50 FL | *- FL |
| 13 | 1 | | *LH FRONT TIE ROD END | Not Damaged | 85.80 FL | *- FL |
| 14 | 1 | | *RH FRONT DRIVE SHAFT | Not Damaged | 921.20 FL | *- FL |
| 15 | 1 | | *STEERING RACK AND PINION | Not Damaged | 1,345.80 FL | *- FL |
| 16 | 1 | | *FRONT BUMPER (AFTER -MARKET) | Dented | 1,250.00 FS | *800.00 FS |
| 17 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 18 | 1 | | *FRONT NUMBER PLATE | Not Damaged | 70.00 FS | *- FS |
| 19 | 1 | | *BRAKE FLUID | Not Damaged | 60.00 FS | *- FS |
| 20 | 1 | | *LH FRONT SPORT RIM | Cut | 1,280.00 FS | *400.00 FS |
| 21 | 1 | | *LH FRONT TYRE | Not Damaged | 450.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 8,774.30 | 2,504.20 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 1,122.86 | 254.84 |
| Total Parts (S\$) | 7,651.44 | 2,249.36 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|--------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS | New | 1,000.00 | 400.00 |
| 2 | SPRAY PAINTING ON AFFECTED AREAS AND PANELS | New | 1,000.00 | 400.00 |
| 3 | CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS | New | 80.00 | 0.00 |
| 4 | APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS | New | 60.00 | 0.00 |
| 5 | REFOCUS AND ADJUST HEADLAMPS ASSY | New | 60.00 | 0.00 |
| 6 | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR | New | 450.00 | 0.00 |
| 7 | ADJUST AND TEST DRIVE WHEEL ALIGNMENT SYSTEM | New | 100.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 2,750.00 | 800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >