

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003900/VVY3M4**Date:** 10/08/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: 60204840  
**Claimant Vehicle No :** SME3938U **Insured Vehicle No :** XE6832R  
 Date of Loss: 22/04/2022 Nature of Claim: TP Claim No: SNM22D202813/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME3938U**  
 Make & Model: MAZDA 3, 1.5 (A) Engine No: P520539438  
 Reg. Date: 27/09/2018 (Man. Year: 2018) Chassis No: JM6BN22A8J0243496  
 Colour: Grey Odometer: 26977 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,142.95	2,082.24	2,060.71	49.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,210.00	2,330.00	65.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,682.95</b>	<b>3,292.24</b>	<b>4,390.71</b>	<b>57.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	7,682.95	2,600.00	5,082.95	66.16
<b>+ GST 7.00/7.00% (S\$)</b>	537.81	182.00	355.81	66.16
<b>Nett Amount (S\$)</b>	<b>8,220.76</b>	<b>2,782.00</b>	<b>5,438.76</b>	<b>66.16</b>

INSPECTION

Date of Assignment: 26/04/2022  
 Date Inspected: 26/04/2022 Inspected At: 56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING  
 Estimated Period of Repair: 5.0 days Repairer: AP AUTOMOTIVE SERVICES PTE LTD

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
<b>Parts:</b>	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME3938U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	1,270.40 F	*1,048.00 FL
2	1		*REAR DOOR HINGE LH	Serviceable	65.10 F	*- FL
3	1		*REAR FENDER LH	Dented	1,174.20 F	*1,174.20 FL
4	1		*REAR FENDER INNER PANEL LH	Repair	428.00 F	*- FL
5	1		*REAR FENDER COWLING LH	Serviceable	160.00 F	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	68.10 F	*68.10 FL
7	1		*REAR FENDER INNER COWLING LH	Serviceable	297.15 F	*- FL
8	1		*SET REAR FENDER COWLING CLIPS	Necessary	80.00 FS	*30.00 FS
9	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*60.00 FS
10	1		*REAR DOOR SEALANT	Necessary	120.00 FS	*60.00 FS
11	1		*REAR DOOR INNER TRIMBOARD CLIP	Necessary	60.00 FS	*30.00 FS
12	1		*SET REAR WINDSCREEN INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
13	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
14	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*REAR WHEELHOUSE SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,142.95</b>	<b>2,540.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	458.06
<b>Total Parts (\$\$)</b>	<b>4,142.95</b>	<b>2,082.24</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	500.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	400.00
3	REMOVE & REFIT INTERIOR UPHOLSTERY AND TRIMS TO FACILITATE REPAIRS	New	400.00	100.00
4	TO APPLY RUST PROOFING	New	180.00	30.00
5	TRANSFER DOOR MECHANISMS	New	80.00	40.00
6	REMOVE AND REFIT REAR WINDOW GLASS	New	80.00	20.00
7	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,540.00</b>	<b>1,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >