



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003902/Kqy3e2	
			Date: 20/05/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YP 4185T	Veh. Inspected	SJW 9516E
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001251MFCV	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	26/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 318I (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WBAPF72090A793437	Colour	METALLIC SILVER
	Odometer	87027 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	FALKEN	7 mm
	L/H Front Tyre	205/55 R16	FALKEN	7 mm
	R/H Rear Tyre	205/55 R16	FALKEN	7 mm
	L/H Rear Tyre	205/55 R16	FALKEN	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/04/2022	Inspection Date	26/04/2022
	Survey held at	Blk 5038 #01-405 Ang mo kio industrial Pk 2		
	Repairer	MASSIVE TRADING & AUTO		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	