

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSN 7092

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	MIRROR SET	SCRAPED / GLASS CRACKED	48.00	48.00
1	BRAKE LEVER	END ABRADED	22.00	22.00
1	HANDLEBAR	BENT	70.00	70.00
1	HANDLEBAR END BALANCER SET	END SCRAPED	44.00	22.00
1	FRONT FENDER	SCRAPED	80.00	80.00
1	FRONT COWLING BASE SUPPORT	SIDE ABRADED	125.00	125.00
1	RH LEG SHIELD	SCRAPED	88.00	88.00
1	RH LEG SHIELD YAMAHA LOGO	SCRAPED	22.00	22.00
1	RH FRONT WINKER LIGHT	ABRADED	45.00	45.00
1	FRONT FOOTREST RH	DENTED / SCRAPED	35.00	35.00
1	REAR BRAKE FOOT PEDAL	ABRADED / BENT	39.00	39.00
1	EXHAUST MUFFLER	SERVICEABLE	350.00	-
1	EXHAUST MUFFLER PROTECTOR	ABRADED	60.00	60.00
1	EXHAUST MUFFLER END CAP	ABRADED	38.00	38.00
1	REAR SIDE BOARD RH	GRAZED	110.00	110.00
	LESS 10% DISCOUNT		-117.60	-80.40
			1,058.40	723.60
	SPECIAL NETT ITEMS			
1	BODY COVER STICKER SET (SN)	NECESSARY	210.00	95.00
			210.00	95.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPLACE AND REPAIR DAMAGED PARTS AND AREAS.		300.00	150.00
			300.00	150.00
	GRAND TOTAL		1,568.40	968.60



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	750.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/SMR22002508/Gty3n2-1

XING GUO QIANG

M.MATAI, AMSAE-A

P

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.