

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: mirage1195@gmail.com, Mobile: 90610543

INVOICE

Lee Zhi Hao
c/o Blk 3023A Ubi Road 1
#01-63
Singapore 408716

Invoice no:	POS0319/22
Date:	13 April 2022
Report no:	319M22.SSH
Vehicle :	JSN7092

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			315.00
SGD(\$): Three hundred and Fifteen only			Grand Total:	315.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



Authorised Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: mirage1195@gmail.com, Mobile: 90610543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 319M22.SSH
Vehicle no : JSN7092

1 REFERENCE

Date of inspection : 17 March 2022
Requested by : Lee Zhi Hao
c/o Blk 3023A Ubi Road 1
#01-63
Singapore 408716
Type of survey : Independent
Repairer : Sin Seng Hong Spray Painting & Services
Blk 3023A Ubi Road 1, #01-63 Singapore 408717
Date of accident : 10 March 2022

2 VEHICLE DATA

Make/model : Yamaha Y15ZR
Chassis no : PMYUG0510J0129230
Engine no : G3D3E129330
Year of manufacture : 2018
Engine capacity : 150 cc
Colour : Blue

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

<u>4 TIRE CONDITION CHECK</u>	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Maxxis	5 mm/Maxxis	80/90-17
Rear tread	: 5 mm/Metzeler	5 mm/Metzeler	110/70-17

5 BRIEF DESCRIPTION OF DAMAGE

Mirror scraped/glass cracked, handlebar bent, RH leg shield scraped, RH rear side board grazed, exhaust muffler protector & end cap abraded, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : **\$1,000.00** (lump sum)
No. of days taken : **Two (2)**

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 319M22.SSH

Vehicle no: JSN7092

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Mirror set	1	scraped/glass cracked	48.00	48.00
Brake lever	1	end abraded	22.00	22.00
Handlebar	1	bent	70.00	70.00
Handlebar end balancer set	1	end scraped	44.00	44.00
Front fender	1	scraped	80.00	80.00
Front cowling base support	1	side abraded	125.00	125.00
RH leg shield	1	scraped	88.00	88.00
RH leg shield Yamaha logo	1	scraped	22.00	22.00
RH front winker light	1	abraded	45.00	45.00
Front footrest RH	1	dented/scraped	35.00	35.00
Rear brake foot pedal	1	abraded/bent	39.00	39.00
Exhaust muffler	1	to reuse	350.00	0.00
Exhaust muffler protector	1	abraded	60.00	60.00
Exhaust muffler end cap	1	abraded	38.00	38.00
Rear side board RH	1	grazed	110.00	110.00
Subtotal of the above			1,176.00	826.00
Discount 10%			117.60	82.60
(Special nett)	Subtotal 1:		1,058.40	743.40
Body cover sticker set	1	necessary	210.00	210.00
Subtotal 2:			210.00	210.00
Total cost of parts:			1,268.40	953.40

B LABOUR

Labour charges to replace and repair damaged parts and areas.	300.00	200.00
Total cost of labour:	300.00	200.00
Total cost of repair:	1,568.40	1,153.40

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$1,153.40

(a) The recommended cost of repair based on lump sum repairs would be **\$1,000.00**

(b) The estimated number of days for the repairs would be **Two (2)**

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:

Liaw Leong San
Licensed Automotive Appraiser

Dated: 13 April 2022























