



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3058X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT HEADLAMP RH (CONSISTENT)	MTG CRACKED	1,999.30	1,715.10
1	FRONT BUMPER ASSY (CONSISTENT)	BENT	466.20	466.20
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	257.40	257.40
1	FRONT BUMPER FOG LIGHT COVER RH (CONSISTENT)	DENTED	25.90	25.90
1	FRONT BUMPER FOG LIGHT RH (CONSISTENT)	MTG CRACKED	237.90	237.90
1	FRONT BUMPER LID RH (CONSISTENT)	BUCKLED / DISTORTED	212.70	212.70
1	FRONT FENDER ARCH GARNISH RH (CONSISTENT)	DISTORTED	150.60	150.60
1	FRONT RETAINER RH (CONSISTENT)	CRACKED	12.40	12.40
	LESS 20% DISCOUNT		-672.48	-615.64
			2,689.92	2,462.56
<b>LABOUR</b>				
	WIRING.		60.00	20.00
	PANEL BEATING.		600.00	300.00
	SPRAY PAINTING.		600.00	400.00
			1,260.00	720.00
<b>GRAND TOTAL</b>			<b>3,949.92</b>	<b>3,182.56</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,500.00</b>

Report Ref No. CS/ASM22003910/Kvy3s2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.