

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22003913/AQCE2**Date:** 04/10/2022REFERENCE

Insured/Claimant:	OH CHUAN AUN	Policy No:	7210013893		
Date of Loss:	21/04/2022	Nature of Claim:	OD	Claim No:	8025413680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDY886G		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC35839
Reg. Date:	05/02/2021 (Man. Year: 2019)	Chassis No:	WAUZZZGA6LA002976
Colour:	Black	Odometer:	24626 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$142,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,641.00	5,849.20	4,791.80	45.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,612.00	4,602.00	4,010.00	46.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,253.00	10,451.20	8,801.80	45.72
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	18,453.00	9,651.20	8,801.80	47.70
+ GST 7.00/7.00% (S\$)	1,291.71	675.58	616.13	47.70
Nett Amount (S\$)	19,744.71	10,326.78	9,417.93	47.70

INSPECTION

Date of Assignment:	27/04/2022		
Date Inspected:	26/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR - RH	Distorted	2,962.00 FS	*2,369.60 FS	
2	6		*GROMMET	Not Necessary	15.00 FS	*- FS	
3	1		*FRONT DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS	
4	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	98.00 FS	*- FS	
5	1		*FRONT DOOR HANDLE - RH	Cut	398.00 FS	*318.00 FS	
6	1		*FRONT DOOR SLIDE VALVE - RH	Not Necessary	25.00 FS	*- FS	
7	1		*FRONT DOOR HANDLE SENSOR - RH	Not Necessary	255.00 FS	*- FS	
8	1		*FRONT DOOR HANDLE CAP - RH	Not Necessary	62.00 FS	*- FS	
9	1		*FRONT DOOR UNDERLAY - RH	Not Necessary	6.00 FS	*- FS	
10	1		*FRONT DOOR UNDERLAY END - RH	Not Necessary	7.00 FS	*- FS	
11	1		*FRONT DOOR MOUNTING BAR - RH	Not Necessary	178.00 FS	*- FS	
12	1		*FRONT DOOR WINDOW APERTURE SEAL - RH OUTER	Not Necessary	151.00 FS	*- FS	
13	1		*FRONT DOOR COVER - RH	Cut	270.00 FS	*216.00 FS	
14	1		*WING MIRROR MOUNTING - RH	Not Necessary	1,130.00 FS	*- FS	
15	1		*WING MIRROR CAP - RH	Repair	203.00 FS	*- FS	
16	1		*REAR DOOR - RH	Distorted	2,962.00 FS	*2,369.60 FS	
17	1		*REAR DOOR OUTER SEAL - RH	Necessary	151.00 FS	*120.40 FS	
18	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS	
19	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS	
20	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS	
21	1		*REAR DOOR CATCH - RH	Damaged	134.00 FS	*104.00 FS	
22	1		*REAR DOOR HANDLE - RH	Not Necessary	398.00 FS	*- FS	
23	1		*REAR DOOR WINDOW APERTURE SEAL - RH OUTER	Not Necessary	151.00 FS	*- FS	
24	1		*REAR DOOR COVER - RH	Cut	238.00 FS	*190.40 FS	
25	1		*REAR WHEEL ARCH COVER - RH	Cut	180.00 FS	*143.60 FS	
26	1		*DUNLOP TYRE (NPA)	Not Necessary	0.00 FS	*- FS	
27	1		*SUNDRIES	Necessary	400.00 FS	*17.60 FS	
					Total Parts (S\$)	10,641.00	5,849.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES AND RHS FRONT WING MIRROR ASSY	New	640.00	560.00
2	TO DISMANTLE AND RENEW RHS FRONT AND REAR DOORS. INSPECT B-PILLAR FOR DAMAGES, REPAIR RHS REAR FENDER. REINSTALL ALL PARTS REMOVEE	New	2,800.00	1,250.00
3	TO RESPRAY RHS FRONT AND REAR DOOR AND REAR RHS REAR FENDER	New	2,700.00	1,800.00
4	TO RENEW RHS FRONT TYRE. CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR RHS B-PILLAR (Supplementary)	New	800.00	250.00
7	TO RESPRAY RHS B-PILLAR (Supplementary)	New	1,200.00	550.00
			Gross Labour Cost (S\$)	8,612.00
				4,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >