9/6/22, 4:08 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III22003914/UEA3Q2

**Date:** 06/09/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0005172

Claimant Vehicle SLN7201A Insured Vehicle No: SLG7308M

No: SEN7201A IIISUreu Venicie No. SEG7300W

Date of Loss: 25/04/2022 Nature of Claim: TP Claim No: MFL2022D0002446

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLN7201A

Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) Engine No: PE20880910

Reg. Date: 16/05/2017 (Man. Year: 2016) Chassis No: JM6GL1071H0115093

Colour: Blue Odometer: 91584 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,922.20	4,237.12	5,685.08	57.30
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,010.00	1,040.00	970.00	48.26
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,932.20	5,277.12	6,655.08	55.77
	Approved Total (Overridden) (S\$)		4,200.00		
	Nett Amount (S\$)	11,932.20	4,200.00	7,732.20	64.80
	+ Car Rental (3.0 x S\$1	100.00/day) (S\$)	300.00		
		(S\$)	4,500.00		
	Liable Amou	nt (50.00%) (S\$)	2,250.00		
	+ Doc/s	Search Fee (S\$)	7.45		
	No	ett Liability (S\$)	2,257.45		

**INSPECTION** 

Date of Assignment: 27/04/2022

Choo Motor Spray Painter (HQ)

Date Inspected: 27/04/2022 Inspected At: 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/6/22, 4:08 PM Adjuster Report

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN7201A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut / Torn	1,466.20 F	*1,211.90 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	66.50 F	*48.50 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	482.30 F	*- FL
4	1		*FRONT BUMPER CHROME MOULDING O/S	Not Necessary	166.80 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*HEADLAMP O/S	Cracked	3,842.60 F	*3,369.80 FL
7	1		*FRONT FENDER O/S	Bent / Dented	662.30 F	*383.70 FL
8	1		*FRONT FENDER INNER SHIELD O/S	Deformed / Torn	246.80 F	*182.50 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
10	1		*FRONT SPORT RIM O/S	Repair	1,201.00 F	*- FL
11	1		*FRONT LOWER ARM O/S	Not Necessary	428.30 F	*- FL
12	1		*FRONT KNUCKLE ARM O/S	Not Necessary	455.80 F	*- FL
13	1		*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	255.00 F	*- FL
14	1		*WIPER WASHER TANK	Not Necessary	182.40 F	*- FL
15	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	366.20 F	*-FL
F=Fra	anchise	part. L=ListIt	emDisc.	-		
				Sub Total (S\$)	9,922.20	5,296.40
	- List Item Discount on L Items 0.00/20.00% (S\$)			0.00	1,059.28	
				Total Parts (S\$)	9,922.20	4,237.12
				-		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO CHECK WIRING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
3	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	0.00
4	TO SPRAY RUST PROOFING	New	60.00	30.00
5	TO RESET & DIAGNOSTIC SYSTEM	New	120.00	80.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	800.00	550.00
	Gr	oss Labour Cost (S\$)	2,010.00	1,040.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >