

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003915/VNY3M4**Date:** 10/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00139362100

Claimant Vehicle No : SKW4831R **Insured Vehicle No :** SMM8844G

Date of Loss: 23/04/2022 Nature of Claim: TP Claim No: SNM22D202827/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW4831R**

Make & Model: AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A) Engine No: CZC288903

Reg. Date: 30/10/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V0GA043725

Colour: White Odometer: 76436 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 ZR17 Rear Tyre Size: 225/45 ZR17

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,421.03	9,683.38	7,737.65	44.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,190.00	2,140.00	49.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,751.03	11,873.38	9,877.65	45.41
Approved Total (Overridden) (\$\$)		9,500.00		
(\$\$)	21,751.03	9,500.00	12,251.03	56.32
+ GST 7.00/7.00% (\$\$)	1,522.57	665.00	857.57	56.32
Nett Amount (\$\$)	23,273.60	10,165.00	13,108.60	56.32

INSPECTION

Date of Assignment: 27/04/2022

Date Inspected: 27/04/2022 Inspected At: H S AUTOMOTIVE SERVICES (KAKI BUKIT)
BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI
BUKIT AUTOHUB
SINGAPORE 417921

Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
Parts:	143	AUDI A3 1.4 TFSI AMBIENTE MY 15 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW4831R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,999.60 F	*1,870.00 FL
2	1		*REAR TAILGATE LOGO (A3)	Necessary	160.77 F	*160.77 FL
3	1		*REAR TAILGATE LOGO (TF81)	Necessary	149.79 F	*149.79 FL
4	1		*REAR TAILGATE LOGO (AUDI, CENTRE)	Necessary	166.70 F	*166.70 FL
5	1		*REAR TAILGATE INNER TRIM BOARD (2PCS)	Cut	600.33 F	*600.33 FL
6	1		*REAR TAILGATE REFLECTOR L/R	N/s Cracked/ O/s Serviceable	1,999.40 F	*999.70 FL
7	2		*REAR TAILGATE DAMPER L/R (NPA)	Serviceable	0.00 F	*- FL
8	1		*REAR TAILGATE WHEATHER STRIP	Deformed	400.67 F	*300.00 FL
9	2		*REAR TAILGATE N/PLATE LAMP	Serviceable	266.80 F	*- FL
10	1		*REAR TAILGATE LOCK	Serviceable	379.45 F	*- FL
11	1		*LH REAR FENDER	Dented	1,999.70 F	*1,999.70 FL
12	1		*LH REAR FENDER INNER SHIELD	Serviceable	379.35 F	*- FL
13	1		*LH REAR FENDER TAIL LAMP	Cracked	900.97 F	*500.97 FL
14	1		*REAR BUMPER	Dented	1,488.90 F	*1,488.90 FL
15	2		*REAR BUMPER RETAINER L/R	Necessary	121.34 F	*121.34 FL
16	2		*REAR BUMPER REVERSE SENSOR ORIGINAL (4PCS)	Cut (2Pieces Only)	935.00 F	*467.50 FL
17	1		*REAR BUMPER REVERSE SENSOR WIRE HARDNESS	Serviceable	273.46 F	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	600.60 F	*600.60 FL
19	1		*REAR END PANEL	Repair	1,300.75 F	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	146.35 F	*- FL
21	2		*REAR EXHAUST PIPE MOUNTING	Serviceable	146.40 F	*- FL
22	1		*REAR TAILGATE INNER TRIM BOARD CLIP	Necessary	76.00 FS	*30.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
24	1		*LH REAR FENDER INNER SHIELD CLIP	Necessary	76.00 FS	*30.00 FS
25	1		*REAR BUMPER CLIP	Necessary	79.00 FS	*30.00 FS
26	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	73.00 FS	*30.00 FS
27	1		*REAR EXHAUST PIPE	Bent	1,800.99 FS	*300.00 FS
28	1		*REAR LOWER BUMPER	Cut	288.96 FS	*288.96 FS
29	1		*REAR BUMPER TOP BRACKET	Cut	273.45 FS	*273.45 FS
30	1		*REAR FENDER AIR VENT	Cut	97.30 FS	*97.30 FS
31	1		*REAR FENDER GLASS SEALANT	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,421.03 10,626.01
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 942.63

Total Parts (\$\$) 17,421.03 9,683.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,600.00	800.00
2	RESPRAY PAINT	New	1,600.00	1,000.00
3	TO TRANSFER COMPONENT	New	180.00	50.00
4	TO REMOVE AND REFIX REAR EXHAUST	New	250.00	70.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
6	TO CHECK WIRING	New	100.00	30.00
7	TO INSTALL REAR REVERSE SENSOR	New	120.00	30.00
8	RUST PROOF	New	120.00	30.00
9	TO REMOVE AND REFIX FENDER GLASS	New	180.00	60.00
Gross Labour Cost (S\$)			4,330.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >