

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003922/APA3Q2**Date:** 04/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070098443
Claimant Vehicle No :	GBC8524M	Insured Vehicle No :	YP3183E
Date of Loss:	23/04/2022	Nature of Claim:	TP
		Claim No:	2266516882SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC8524M		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Engine No:	1KD2361640
Reg. Date:	13/01/2014 (Man. Year: 2013)	Chassis No:	JTFHT02P200131085
Colour:	Silver	Odometer:	231618 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,393.96	1,819.92	574.04	23.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	550.00	830.00	60.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,773.96	2,369.92	1,404.04	37.20
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,773.96	1,900.00	1,873.96	49.66
+ GST 7.00/7.00% (S\$)	264.18	133.00	131.18	49.66
Nett Amount (S\$)	4,038.14	2,033.00	2,005.14	49.66
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,360.45		
Global Sum Settlement (S\$)		2,350.00		

INSPECTION

Date of Assignment:	28/04/2022		
Date Inspected:	28/04/2022	Inspected At:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Dented	1,765.00 FL	*1,765.00 FL
2	1		*TOYOTA LOGO	Necessary	55.10 FL	*55.10 FL
3	1		*HIACE LOGO	Necessary	65.10 FL	*65.10 FL
4	1		*LOGO	Necessary	78.10 FL	*78.10 FL
5	1		*70KM/H STICKER	Necessary	27.99 FS	*10.00 FS
6	2		*BOOT COVER HINGE	Bent	296.60 FL	*296.60 FL
7	1		*BOOT COVER LOCK INNER	Not Necessary	213.40 FL	*- FL
8	1		*REAR WINDSCREEN GLASS SEAL	Necessary	55.00 FS	*55.00 FS
9	1		*REAR WINDSCREEN SEALANT	Necessary	85.00 FS	*60.00 FS
					Sub Total (S\$)	2,641.29 2,384.90
					- List Item Discount on L Items 10.00/25.00% (S\$)	247.33 564.98
					Total Parts (S\$)	2,393.96 1,819.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	550.00	200.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	580.00	200.00
3	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
Gross Labour Cost (\$\$)			1,380.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >