



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22003930/Kvy3e2 Date: 23/09/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 7684D	Veh. Inspected	PC 9681U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2201116/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	05/04/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GDH2232002871	Colour	METALLIC SILVER
Odometer	100767 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	DUNLOP	6 mm
L/H Front Tyre	195 R15X8	DUNLOP	6 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	7 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	7 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	04/04/2022	Inspection Date	01/08/2022
Survey held at	Blk 01 Sin Ming industrial Sector C #01-135		
Repairer	A T AUTO CONSULTANT		
5a. Remarks			
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days