

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003932/AYA3Q2**Date:** 25/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900247426-02
Claimant Vehicle No :	SLQ5730L	Insured Vehicle No :	GBK365R
Date of Loss:	25/04/2022	Nature of Claim:	TP
		Claim No:	4593629073SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5730L	Engine No:	3ZRB953445
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600096834
Reg. Date:	14/07/2017 (Man. Year: 2016)	Odometer:	131882 km
Colour:	White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Conquest 6 mm	Rear Left Side:	Conquest 6 mm
Front Right Side:	Conquest 6 mm	Rear Right Side:	Conquest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,751.75	7,412.25	5,339.50	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,270.00	1,610.00	55.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,631.75	8,682.25	6,949.50	44.46
Approved Total (Overridden) (S\$)		6,900.00		
Nett Amount (S\$)	15,631.75	6,900.00	8,731.75	55.86
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/04/2022	
Date Inspected:	26/04/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,186.00 FL	*1,186.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	183.00 FL	*183.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	75.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Cracked	125.00 FL	*125.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	495.00 FL	*495.00 FL
6	1		*FRONT BUMPER SIDE SUPPORT BRACKET LH	Bent	225.00 FL	*225.00 FL
7	1		*FRONT BUMPER SIDE SUPPORT BRACKET SPONGE LH	Cracked	159.00 FL	*159.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	284.00 FL	*284.00 FL
9	1		*FRONT BUMPER FOG LAMP LH	Cracked	379.00 FL	*379.00 FL
10	1		*FRONT BUMPER FOG LAMP BRACKET LH	Not Necessary	140.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP OUTER GARNISH LH	Not Necessary	208.00 FL	*- FL
12	1		*FRONT BUMPER LOWER LIP	Deformed	285.00 FL	*285.00 FL
13	1		*FRONT BUMPER LOWER COVER	Not Necessary	322.00 FL	*- FL
14	1		*FRONT GRILLE	Cracked	895.00 FL	*598.00 FL
15	1		*FRONT GRILLE LOGO	Necessary	1,015.00 FL	*110.00 FL
16	1		*FRONT GRILLE BRACKET	Not Necessary	66.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Repair	730.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	320.00 FL	*320.00 FL
19	1		*FRONT SUPPORT PANEL SIDE GUARD GARNISH LH	Not Necessary	218.00 FL	*- FL
20	1		*FRONT SUPPORT PANEL CENTER BEAM	Not Necessary	189.00 FL	*- FL
21	1		*FRONT FENDER LH	Dented	987.00 FL	*987.00 FL
22	1		*FRONT FENDER INNER COWLING LH	Deformed	572.00 FL	*349.00 FL
23	1		*FRONT FENDER BRACKET INNER LH	Bent	206.00 FL	*95.00 FL
24	1		*FRONT HEADLAMP LH	Cracked	3,512.00 FL	*3,512.00 FL
25	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	239.00 FL	*- FL
26	1		*HEADLAMP WIRE HARNESS	Not Necessary	856.00 FL	*- FL
27	1		*FRONT BUMPER LOWER COVER TOP	Not Necessary	224.00 FL	*- FL
28	1		*AIR DUCT LH	Deformed	139.00 FL	*139.00 FL
29	1		*FRONT ABSORBER TANK	Deformed	412.00 FL	*372.00 FL
30	1		*BONNET	Repair	1,983.00 FL	*- FL
31	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
32	2		*FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*FRONT FENDER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
34	1		*FRONT BUMPER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
35	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,909.00	9,863.00
- List Item Discount on L Items 25.00/25.00% (\$)	4,157.25	2,450.75
Total Parts (\$)	12,751.75	7,412.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,600.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	600.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	200.00	40.00
Gross Labour Cost (\$\$)			2,880.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >