

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003936/Rqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 11/05/2022 SINGAPORE 068811 ATTN: LEONG JACQUELINE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 1058S** FBS 9405H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03YD3 Excess (\$) 0.00 LEONG JACQUELINE **Assign Date** 27/04/2022 Assign From **Vehicle Particulars & Condition** 2. YAMAHA AEROX155 CVT 155 Make & Model C.C HIDDEN 2021 Engine No. Year of Reg. MH3SG6410LJ006293 **GREY** Chassis No. Colour Odometer 11355 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/80-14 MICHELIN 3 mm L/H Front Tyre mm 140/70-14 **MICHELIN** R/H Rear Tyre 3 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 07/04/2022 28/04/2022 (02:04 PM) Inspect Date / Time Accident Date **BIKE DYNAMIC CENTRE** Survey held at BLK 6 DEFU LANE 10 #01-55 SINGAPORE 539187 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22003936/Rqy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

DEOD Anta Ornantiant OAE Utamand Annualism

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days