

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD CS3/LPC22003949/Ety3e2 Ref: 300 BEACH ROAD #17-04/07 THE CONCOURSE Date: 11/05/2022 SINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. YP 8353Z YP 9782L Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 21/22/22/VC05/025715 Excess (\$) 0.00 **GERALD POH Assign From Assign Date** 27/04/2022 2. **Vehicle Particulars & Condition** ISUZU NPR85UH5AA 3.0 SMT Make & Model c.c 2999 **TURBO** Engine No. **HIDDEN** Year of Reg. 2017 Chassis No. JAANPR85HH7100986 Colour SILVER 77451 KM Odometer **IN ORDER** Steering STANDARD ALLOY RIM **IN ORDER Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** 195R15C YOKOHAMA 4 mm R/H Front Tyre YOKOHAMA L/H Front Tyre 195R15C 4 mm R/H Rear Tyre 195R15C YOKOHAMA 4 mm 195R15C YOKOHAMA L/H Rear Tyre 4 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information Accident Date** 22/04/2022 Inspect Date / Time 27/04/2022 (08:33 PM) KOH KOCK LEONG ENTERPRISE PL Survey held at NO.4 TUAS DRIVE 2 SINGAPORE 638638 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE

Report Ref No. CS3/LPC22003949/Ety3e2

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser