

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22003951/VNY3E2

**Date:** 01/09/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00230422100  
**Claimant Vehicle No :** SKZ6966G **Insured Vehicle No :** SLN5560B  
Date of Loss: 25/04/2022 Nature of Claim: TP Claim No: SNM22D202828C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ6966G**  
Make & Model: HONDA CITY, 1.5 CVT (A) Engine No: L15Z12719374  
Reg. Date: 29/01/2016 (Man. Year: 2015) Chassis No: MRHGM6660GP000414  
Colour: Blue Odometer: 153005 km  
Engine Capacity: 1497 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16  
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm  
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,023.52	2,621.84	2,401.68	47.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	1,430.00	3,000.00	67.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,453.52</b>	<b>4,051.84</b>	<b>5,401.68</b>	<b>57.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,453.52</b>	<b>3,250.00</b>	<b>6,203.52</b>	<b>65.62</b>

### INSPECTION

Date of Assignment: 15/06/2022  
Date Inspected: 28/04/2022 Inspected At: JEW Motors (HQ)  
60 Jalan Lam Huat Carros Centre #03-72  
Singapore 737869  
Estimated Period of Repair: 5.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2022)
<b>Parts:</b>	143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ6966G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	531.00 FL	*531.00 FL
2	1		*BOOTLID CITY LOGO	Necessary	17.80 FL	*17.80 FL
3	1		*BOOTLID CENTRE LOGO	Necessary	28.00 FL	*28.00 FL
4	1		*BOOTLID I-VTEC LOGO	Necessary	26.00 FL	*26.00 FL
5	1		*BOOTLID RH LAMP ASSY	Cracked	98.20 FL	*98.20 FL
6	1		*BOOTLID LH LAMP ASSY	Cracked	98.20 FL	*98.20 FL
7	1		*BOOTLID CHROME MOULDING	Serviceable	94.30 FL	*- FL
8	1		*BOOTLID INNER TRIM	Cut	89.20 FL	*89.20 FL
9	1		*BOOTLID RH HINGE	Serviceable	66.70 FL	*- FL
10	1		*BOOTLID LH HINGE	Serviceable	66.70 FL	*- FL
11	1		*BOOTLID RH NUMBER PLATE LAMP ASSY	Serviceable	18.60 FL	*- FL
12	1		*BOOTLID LH NUMBER PLATE LAMP ASSY	Serviceable	18.60 FL	*- FL
13	1		*BOOTLID REVERSE CAMERA	Serviceable	387.90 FL	*- FL
14	1		*BOOTLID LOCK	Jammed	56.80 FL	*56.80 FL
15	1		*BOOTLID LOCK CATCH	Serviceable	12.30 FL	*- FL
16	1		*BOOTLID WEATHERSTRIP	Deformed	78.40 FL	*78.40 FL
17	1		*REAR BUMPER	Dented	463.70 FL	*463.70 FL
18	1		*REAR BUMPER RH RETAINER	Necessary	15.80 FL	*15.80 FL
19	1		*REAR BUMPER LH RETAINER	Necessary	15.80 FL	*15.80 FL
20	1		*REAR BUMPER RH BRACKET	Necessary	29.60 FL	*29.60 FL
21	1		*REAR BUMPER LH BRACKET	Necessary	29.60 FL	*29.60 FL
22	1		*REAR BUMPER RH REFLECTOR	Necessary	66.90 FL	*66.90 FL
23	1		*REAR BUMPER LH REFLECTOR	Serviceable	66.90 FL	*- FL
24	1		*RH TAILLAMP ASSY	Cracked	205.70 FL	*205.70 FL
25	1		*RH TAILLAMP PANEL	Repair	115.00 FL	*- FL
26	1		*SET RH TAILLAMP LOCK CLIPS	Necessary	22.00 FL	*22.00 FL
27	1		*LH TAILLAMP ASSY	Cracked	205.70 FL	*205.70 FL
28	1		*LH TAILLAMP PANEL	Repair	115.00 FL	*- FL
29	1		*SET LH TAILLAMP LOCK CLIPS	Necessary	22.00 FL	*22.00 FL
30	1		*END PANEL	Dented	399.30 FL	*399.30 FL
31	1		*END PANEL TOP COVER	Cut	109.40 FL	*109.40 FL
32	1		*REAR WINDSCREEN GLASS RUBBER SEAL	Serviceable	65.60 FL	*- FL
33	1		*REAR LH FENDER	Repair	766.90 FL	*- FL
34	1		*REAR LH FENDER QUARTER GARNISH	Serviceable	14.90 FL	*- FL
35	1		*REAR LH FENDER INNER TRIM	Cut	87.90 FL	*87.90 FL
36	1		*REAR LH FENDER SPLASH SHIELD	Serviceable	38.10 FL	*- FL
37	1		*SPARE TYRE COVER BOARD	Cut	80.30 FL	*80.30 FL
38	1		*EXHAUST SILENCER	Repair	457.60 FL	*- FL
39	1		*EXHAUST SILENCER GASKET	Serviceable	22.00 FL	*- FL
40	1		*SET BOOTLID CHROME MOULDING CLIPS	Necessary	80.00 FS	*30.00 FS
41	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	70.00 FS	*30.00 FS
42	1		*REAR NUMBER PLATE	Serviceable	70.00 FS	*- FS
43	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
44	1		*SET REAR BUMPER REVERSE SENSOR	Cut	380.00 FS	*200.00 FS
45	1		*END PANEL SEALANT	Necessary	70.00 FS	*40.00 FS
46	1		*SET END PANEL TOP COVER CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LH FENDER SEAL	Not Necessary	70.00 FS	*- FS
48	1		*SET REAR LH FENDER INNER TRIM CLIPS	Necessary	45.00 FS	*20.00 FS
49	1		*SET REAR RH FENDER INNER TRIM CLIPS	Necessary	45.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					6,044.40	3,177.30
- List Item Discount on L Items 20.00/20.00% (S\$)					1,020.88	555.46
Total Parts (S\$)					5,023.52	2,621.84

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO PROVIDE WORKMANSHIP CUT / WELD AND REPLACING OF PARTS	New	1,500.00	600.00
2	SPRAY PAINT ON AFFECTED AND CONSISTENT AREAS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	30.00
4	APPLY RUST CHEMICAL ON AFFECTED AREAS	New	100.00	30.00
5	REMOVE AND REPLACE BOOTLID REVERSE CAMERA	New	150.00	30.00
6	REMOVE AND REPLACE BOOTLID INNER MECHANISM	New	120.00	40.00
7	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	240.00	0.00
8	REMOVE AND REPLACE REAR INNER GARNISH AND TRIM	New	350.00	70.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	100.00	30.00
10	REMOVE AND REFIT PETROL TANK, PIPES AND HOSES	New	220.00	0.00
11	REMOVE AND REFIT ROOF LINING, SEATS AND CARPET TO REPLACE REAR FENDER	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,430.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >