



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22003954/Kqy3q2

Date: 28/10/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|-------------------|-----------------------|------------|
| Insured Veh. | SMV 9059C | Veh. Inspected | SMK 1675J |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10014841/CD | Excess (\$) | 0.00 |
| Assign From | SHAFAWATI MD RABU | Assign Date | 27/04/2022 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|--------------------|
| Make & Model | TOYOTA CAMRY (A) | c.c | 1998 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | MR2BN3HK204001914 | Colour | METALLIC DARK GREY |
| Odometer | 33773 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|-------------|---------|
| R/H Front Tyre | 205/65 R16 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 205/65 R16 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 205/65 R16 | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 205/65 R16 | BRIDGESTONE | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 20/04/2022 | Inspection Date | 28/04/2022 |
| Survey held at | CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**