S. REC. BY: Taypon REF: CS AG12	2003957 Toy3
	SIGNMENT
om; Date:	Veh No: SLM 520E Yr Regn: 2017, March
limated Cost:	Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DIATE I WS I TP RES I OD RES I EVA I INV I MV	Truck / Trailer or
o Inspect Vehicle No:	Make: blonder City 1-5 c.c 1497
Workshop m/s	Make: florder City 1-5 c.c 1497  Colour Gwy A/C: Insured / Std / NI / NA
	Sp.Reading / Sp.Re
sured;	Eng/No:
olicy No.	C/No: MRHGM 6660 + 4P000556
laims No.	Gen. Cond: Good / Fair / Poor / Burnt
um Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
ake of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 7
emark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO/YOKO OF Westake. Westlehe
al. or Market Value: 958K	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
SIA / PR Seen: Consistent? : Yes or No	L/Bal. C. mm L/Bal. G mm
st. Repairs days Res.: Yes or No	D.O.A. D.O.I. 28/4727
um Sum: % 3 Val.: Yes or No	Survey held at TSC Auch
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / O	
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	
1	1 .
· · · · · · · · · · · · · · · · · · ·	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Date/Time, File Pass to? : Preli. Report  : Final Report	Decument
- Tom Report	Resurvey No. of Trip: Survey Fee:
; Final Report	Resurvey No. of Trip:  Survey Fee:  Transportation:
: Final Report  Date/Time, File Return to?  Add	Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )S+RSSI
: Final Report Date/Time, File Return to?	Resurvey No. of Trip:  Survey Fee:  Transportation:  See:  Survey Fee:  Transportation:  See:  Survey Fee:  Transportation:  See:  Transportation:  See:  See:  See:  Survey Fee:  Transportation:  See:  See:  See:  See:  Survey Fee:  Transportation:  See:  See:  See:  See:  Survey Fee:  Transportation:  See:  Se

## TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

SLM520E Honda City			Estimated
			Parts Price
No	Qty	Parts Description	\$ 589.70 dk
1	1	Rear bumper assy	\$ 39.60 ell \$ 37.40 de
2	2	Rear bumper bracket	\$ 37.40
3	2	Rear bumper side retainer	¢ 180.60 CA1
4	2	Rear bumper reflector	\$ 683.40 <b>b</b> +
5	1	Rear bootlid assy	\$ 36.30 ⊀
6	2	Rear bootlid rubber stopper	\$ 125.70 <b>\</b>
7	2	Rear bootlid hinges	\$ 167.90
8	1	Rear bootlid weatherstrip	\$ 105.40 bt
9	1	Rear bootlid lock mechanism	\$ 67.40 <b>X</b>
10	1	Rear bootlid lock catch	\$ 68.30 ABC
11	1	Rear bootlid centre logo	\$ 56.80 row
12	1	Rear bootlid city emblem	\$ 48.30 W
13	1	Rear bootlid IVTEC emblem	\$ 176.20 X
14	1	Rear bootlid outer chrome garnish	\$ 172.60 ×
15	1	Rear bootlid inner board	\$ 212.80 cut
16	1	Rear left bootlid taillamp	\$ 212.80
17	1	Rear right bootlid taillamp	\$ 446.20
18	1	Rear left taillamp	\$ 212.80 wh \$ 446.20 wh \$ 446.20 wh
19	1	Rear right taillamp	\$ 480.60 14
20	1	Rear end lower panel	\$ 88.10
21	1	Rear end lower panel top garnish	\$ 88.00 ⋉
22	2	Rear no plate lamp	\$ 880.90 buc
23	1	Rear floor panel	\$ 168.50 cm
24	1	Rear spare tyre top board	\$ 951.50 X R
25	1	Rear exhaust muffler assy	\$ 36.30 ×
26	2	Rear exhaust muffler rubber mounting	
			-
		Less 20%	
			\$ 5,261.20
		Special Nett Items	\$ 50.00 30 me
1	10	Rear bumper clips	
2	8	Rear bootlid inner board clips	
3	4	Rear bootlid outer chrome garnish clips	
4	4	Rear end lower panel top garnish clips	\$ 30.00 20 ml
5	1	Rear end lower panel sealant	\$ 120.00 404/
6	1	Rear floor panel sealant	\$ 120.00 K
7	1	Rear floor panel insulator pad	\$ 150.00 love
8	4	Rear bumper reverse sensor	\$ 600.00 Zognm
9	1	Rear view camera	\$ 450.00 <b>(</b>
10	1	Rear no plate with garnish	\$ 100.00 ~
400		-	\$ 1,680.00

\$ 6,941.20

**Total parts** 

#### TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

الالط	134UE	Honda City		Estimated		
	0.1	De to Description		Parts Price		
No	CALLED AND AND AND AND AND AND AND AND AND AN	Parts Description	\$	589 90 de		
1	1	Front bumper assy	\$	66.30 de/		
2	l	Front bumper left bracket	\$	66.30 ⊀		
3	1	Front bumper right bracket	\$	63.20 di		
4	1	Front bumper left side retainer	\$	63.201		
5	1	Front bumper right side retainer	\$	296.80em		
6	1	Front grille assy	\$	68.60 ng/		
7	1	Front grille emblem	\$	193.50K		
8	1	Fron bumper lower grille assy		792.40 K		
9	1	Front bonnet assy	\$			
10	1	Front bonnet insulator	\$	128.20 4		
11	1	Front right headlamp	\$	428.30 ove		
12	1	Front left headlamp	\$	428.30 er		
13	1	Front right headlamp bracket	\$	68.00 <b>&lt;</b>		
14	1	Front left headlamp bracket	\$	68.00×		
15	1	Front support panel assy	\$	492.80 × R		
16	1	Front support panel top garnish	\$	179.10 🗡		
17	1	Front bonnet lock mechanism	\$	155.70 \$		
18	1	Front bumper tow cover	\$	68.80⊀		
19	1	Front bumper reinforcement	\$	311.50 x		
20	1	Front left fog lamp	\$	252.10 cm		
21	1	Front right fog lamp	\$	252.10 📉		
22	1	Front left fog lamp cover	\$	68.50		
23	1	Front right fog lamp cover	_\$_	68.50 x		
			\$	5,170.10		
		Less 20%	_\$_	1,034.02		
				4,136.08		
		Special Nett Items		2		
1	10	Front bumper clips	\$	مره في 50.00		
2	4	Front grille clips	\$	20.00 CO ARC		
3		Front no plate with garnish	\$	100.00 ₩		
1	1 set	Front bumper lower grille clips	\$	40.00		
5	6	Front support panel top garnish clips	\$	30.00×		
5	1 set	Front bonnet insulator clips	\$	40.00 K		
		<del>-</del>	\$	280.00		
	,	Total parts	\$	4,416.08		

#### **TSL Auto Garage** Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

### **SLM520E Honda City**

No	Description		Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$	1,000.00 \$ 3 ° °
3	To putty and spray painting front portion.	\$	1.000 00 = 300
4	To check wiring and focus front headlamp.	\$	50.00 3~
	To remove and install front bonnet lock mechanism.	\$	80.00 ×
6	To apply anti rust proofing to front affected area.	\$	140.00×
	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$	1,400.00/000
8	To putty and spray painting rear portion.	\$	1,400.00 900
9	To check rear lighting and wiring.  To remove and install and lighting.	\$	50.00 go
10	To remove and install rear bootlid lock mechanism.  To remove and install rear solutions.	\$	80.00 GO
11	To remove and install rear exhaust muffler assy.  To repair straighten and align both rear fenders.	\$	120.00 60
12	To remove and install rear inner garnish and trim to facilitate the repair.	\$	350.00 <b>Y</b>
		\$	140.00 60
13	To apply anti rust proofing to rear affected area.		
-	To remove and install rear view come.	\$	140.00 40
	To remove and install rear humper reserve	\$	80.00 30
	alignment	\$	80.0030
7	Towing service.	\$	350.00 X
	Total labour :	\$ <b>\$</b>	100.00× 6,560.00

Total parts: \$ 11,357.28 Total labour : \$ 6,560.00

Total repair cost: \$ 17,917.28

Taylin 97495749

WP 28/4/12 C320pm.

L/r Resney after reporr

taylin @ (Whanto.com)

Oddys

# LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ेग्रह: