

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003958/GVY3N2**Date:** 29/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00106592100
<b>Claimant Vehicle No :</b>	SDT8828Z	<b>Insured Vehicle No :</b>	SMT9304E
Date of Loss:	25/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202844/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDT8828Z</b>	Engine No:	F1783102B48B20A
Make & Model:	BMW 420I, 2.0 Gran Coupe (A)	Chassis No:	WBA4H32000BP27715
Reg. Date:	27/09/2018 (Man. Year: 2018)	Odometer:	55553 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/40R18	Rear Tyre Size:	255/40R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,087.88	1,582.48	505.40	24.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	400.00	100.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,587.88</b>	<b>1,982.48</b>	<b>605.40</b>	<b>23.39</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	181.15	138.77	42.38	23.39
<b>Nett Amount (\$\$)</b>	<b>2,769.03</b>	<b>2,121.25</b>	<b>647.78</b>	<b>23.39</b>

**INSPECTION**

Date of Assignment:	27/04/2022	
Date Inspected:	28/04/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$1,982.49

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
<b>Parts:</b>	143	BMW 420I 2.0 Gran Coupe (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDT8828Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,341.05 FL	*1,341.05 FL
2	1		*REAR BUMPER REFLECTOR RH	Not Necessary	45.60 FL	*- FL
3	1		*REAR BUMPER LOWER GARNISH	Broken	255.40 FL	*255.40 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	470.25 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	45.70 FL	*- FL
6	4		*PARKING SENSOR RING	Necessary	32.20 FL	*32.20 FL
7	1		*REAR BUMPER CENTRE GARNISH	Broken	71.50 FS	*71.50 FS
8	1		*REAR WATER GUTTER COVER RH	Broken	45.20 FS	*45.20 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,306.90</b>	<b>1,745.35</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	219.02	162.87
<b>Total Parts (\$\$)</b>	<b>2,087.88</b>	<b>1,582.48</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	200.00	200.00
2	TO SPRAY REAR BUMPER	New	300.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>500.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >