

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003960/RVY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00084012100

Claimant Vehicle No : SLZ5811P **Insured Vehicle No :** SJS6199C

Date of Loss: 12/04/2022 Nature of Claim: TP Claim No: SNM22D202860/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ5811P**

Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A) Engine No: 8ARZ116307

Reg. Date: 10/05/2018 (Man. Year: 2018) Chassis No: JTEKB3GH80J001807

Colour: Black Odometer: 63871 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,338.50	360.00	1,978.50	84.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	500.00	530.00	51.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,368.50	860.00	2,508.50	74.47
+ GST 7.00/7.00% (\$\$)	235.80	60.20	175.60	74.47
Nett Amount (\$\$)	3,604.30	920.20	2,684.10	74.47

INSPECTION

Date of Assignment: 27/04/2022

Date Inspected: 13/05/2022 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,143.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 G GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ5811P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	904.00 FL	*- FL
2	1		*REAR BUMPER SPONGE	Not Necessary	160.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*REAR BUMPER LOWER	Scratched	480.00 FL	*480.00 FL
5	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
6	4		*REVERSE SENSOR	*Check	1,524.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,118.00	480.00
- List Item Discount on L Items 25.00/25.00% (S\$)	779.50	120.00
Total Parts (S\$)	2,338.50	360.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	500.00	250.00
2	TO RESPRAY AFFECTED AREAS	New	500.00	250.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00
Gross Labour Cost (\$)			1,030.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >